

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00040	Policy	POL-89893920
Vehicle	2022 Toyota Corolla	VIN	JT7C1L9USKZUA6LR0
Location	Penang	Date	2026-05-19
Weather	Rain	Road	Dry Asphalt

Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Left fender, Hood, Tail lamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 26 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 7,176.

Damage Area	Severity	Recommendation
Right door	Minor	Replace
Rear bumper	Minor	Replace
Tail lamp	Major	Repair
Hood	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.