

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00042	Policy	POL-20417683
Vehicle	2020 Nissan X-Trail	VIN	JT8NGXV5XXXTHJEDV
Location	Penang	Date	2026-05-08
Weather	Clear	Road	Wet Asphalt

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Rear bumper, Tail lamp, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 10 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 22,617.

Damage Area	Severity	Recommendation
Rear bumper	Major	Replace
Front bumper	Major	Replace
Left headlamp	Minor	Replace
Left fender	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.