

# Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

|              |                     |        |                   |
|--------------|---------------------|--------|-------------------|
| Claim Number | CLM-2026-00044      | Policy | POL-16639072      |
| Vehicle      | 2023 Hyundai Tucson | VIN    | JT84X458Z116U4M2D |
| Location     | Ipoh                | Date   | 2026-05-04        |
| Weather      | Cloudy              | Road   | Wet Asphalt       |

## Coverage Assessment

The insured reported a flood exposure involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Right door, Left headlamp, Rear bumper. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

### Repair Summary

- OEM parts recommended where available.
- Estimated labor: 20 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 25,827.

| Damage Area   | Severity | Recommendation |
|---------------|----------|----------------|
| Left headlamp | Moderate | Repair         |
| Right door    | Minor    | Repair         |
| Rear bumper   | Major    | Replace        |
| Left fender   | Major    | Repair         |

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.