

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00045	Policy	POL-78193077
Vehicle	2022 Honda Civic	VIN	JTCWJ7KVJXZX3AC7Y
Location	Penang	Date	2026-05-27
Weather	Cloudy	Road	Urban Road

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Hood, Front bumper, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 7 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 22 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 13,357.

Damage Area	Severity	Recommendation
Hood	Major	Replace
Tail lamp	Major	Replace
Left headlamp	Major	Replace
Left fender	Minor	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.