

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00009	Policy	POL-93552135
Vehicle	2023 Honda Civic	VIN	JTAG2SRW6RLVTRE7U
Location	Seremban	Date	2026-05-19
Weather	Cloudy	Road	Concrete

Coverage Assessment

The insured reported a multiple panel damage involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Tail lamp, Front bumper, Left fender, Left headlamp. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 5 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 10 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 27,278.

Damage Area	Severity	Recommendation
Rear bumper	Moderate	Repair
Tail lamp	Minor	Inspect
Front bumper	Moderate	Repair
Left fender	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.