

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00029	Policy	POL-20000026
Vehicle	2023 Toyota Corolla	VIN	JTGLXU26BHKFB0UKZ
Location	Seremban	Date	2026-05-10
Weather	Overcast	Road	Wet Asphalt

Coverage Assessment

The insured reported a front-left impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Rear bumper, Hood, Tail lamp, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 6 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 26 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 20,115.

Damage Area	Severity	Recommendation
Left fender	Minor	Replace
Tail lamp	Minor	Inspect
Front bumper	Minor	Replace
Rear bumper	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.