

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00030	Policy	POL-35830049
Vehicle	2025 Honda Civic	VIN	JTM1ZPKA9P6H1YB4R
Location	Penang	Date	2026-05-22
Weather	Cloudy	Road	Urban Road

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Right door, Front bumper, Hood, Left fender. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 20 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 25,921.

Damage Area	Severity	Recommendation
Tail lamp	Minor	Repair
Right door	Minor	Inspect
Left fender	Minor	Replace
Hood	Major	Replace

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.