

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00035	Policy	POL-80535198
Vehicle	2025 Toyota Corolla	VIN	JTN0HBK7AF7WM0D1F
Location	Kuala Lumpur	Date	2026-05-05
Weather	Overcast	Road	Wet Asphalt

Coverage Assessment

The insured reported a rear-end collision involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Left headlamp, Hood, Left fender, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 3 business days.

Repair Summary

- OEM parts recommended where available.
- Estimated labor: 19 hours.
- Paint and refinishing required.
- Preliminary repair estimate: RM 26,895.

Damage Area	Severity	Recommendation
Hood	Moderate	Repair
Right door	Minor	Replace
Left headlamp	Major	Inspect
Tail lamp	Moderate	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.