

Motor Insurance Claim Assessment

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00037	Policy	POL-14965841
Vehicle	2020 Nissan X-Trail	VIN	JT87GNX9X04GA8WS1
Location	Ipoh	Date	2026-05-12
Weather	Rain	Road	Urban Road

Coverage Assessment

The insured reported a right-side impact involving the above vehicle. A licensed adjuster performed a visual inspection. Observed damage includes Hood, Rear bumper, Front bumper, Right door. Structural measurements were not performed in this synthetic sample. Coverage review indicates the loss is consistent with the reported event. Estimated repair duration is 4 business days.

- Repair Summary
- OEM parts recommended where available.
 - Estimated labor: 28 hours.
 - Paint and refinishing required.
 - Preliminary repair estimate: RM 17,236.

Damage Area	Severity	Recommendation
Left fender	Major	Replace
Left headlamp	Minor	Replace
Hood	Major	Repair
Front bumper	Minor	Inspect

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.