

Motor Vehicle Accident Report

NorthStar Mutual Insurance Group (Fictional)

Claim Number	CLM-2026-00027	Policy	POL-22041634
Vehicle	2023 Mercedes-Benz GLC	VIN	JTV2NKXPM6SKY58R0
Location	Ipoh	Date	2026-05-07
Weather	Rain	Road	Urban Road

Incident Narrative

At approximately 15:01, the reporting driver stated the vehicle was travelling on an urban roadway in Ipoh.

The collision resulted in a right-side impact. Responding personnel documented visible damage affecting Rear bumper, Left headlamp, Front bumper.

No injuries were reported in this synthetic example. The vehicle was transported by tow truck.

Contributing factors noted: failure to yield, reduced visibility, and wet road conditions where applicable.

Damage Area	Severity	Recommendation
Front bumper	Minor	Replace
Left headlamp	Major	Replace
Hood	Moderate	Repair
Rear bumper	Major	Repair

Adjuster/Officer Remarks: This document is a fully synthetic sample created for software testing, OCR evaluation, and demonstration purposes. It does not describe a real incident or policy.