Repair Order

Accident No		
5/11/2022	Date of the accident	
Workshop Detail	11/05/2022	
Aqaba كراج محمود سالم العقبة	Vehicle Owner Name	
Request Number	testing 51122	
23082202 /3R	VIN	
Accident Type	HHKHAKDABBC888212	
Comprehensive	Plate No	
Damage Poi	22013	
21,	Car Details	
PO Note	Toyota 4Runner	
_	Year	
Pricing Type	2020	
Pricing and Providing	Created By	
	التامين الاردنية (AM 50:50:9 022	
Faulty Company Name	_	

Task Details

Faulty Company Name

Туре		Labour Price	Labour Time	Task Description	#
Body Repair		360 JOD	5 (Day(s)	1	1
		Ordered I	Parts		
	Supplier	Received On	Quantity	Name	#

No record found