# **SBOM VALIDATION REPORT**

### **Validation Parameters**

Workcenter Plant Reference:	001
Workcenter Production Area Reference:	01
Workcenter Use Single Final Assembly:	Yes

Report generated on: 2025-06-24 16:51:07

Work Center Validation Results				
Validation Item	Input Value	XML Value	Status	
Workcenter Plant Reference mismatch	001	01	Mismatch	
Workcenter Production Area Reference m	i <b>\$</b> 1hatch	002	Mismatch	

### **Twisted Wires Validation Results**

**FAILURE: Mismatches found between SBOM and Excel** 

#### **Mismatch Details:**

- \* Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

## Wire Length Validation Results

**FAILURE: Wire length mismatches found** 

## Wire Length Mismatch Details:

- \* Wire length mismatch for 45(2): XML=687.0, Excel=707.0
- \* Wire length mismatch for 44(1): XML=1215.0, Excel=115.0
- \* Wire 53(1) not found in Excel Wires Lengths sheet

## **Validation Summary**

Validation Category	Issues Found	Status
Work Center Attributes	2	FAIL
Twisted Wires Validation	12	FAIL
Wire Length Validation	3	FAIL
OVERALL VALIDATION STATUS	17	FAIL

This is an automatically generated validation report For any discrepancies, please contact the validation team