SBOM VALIDATION REPORT

Validation Parameters

Workcenter Plant Reference:	002
Workcenter Production Area Reference:	01
Workcenter Use Single Final Assembly:	Yes

Report generated on: 2025-05-26 02:01:02

Work Center Validation Results					
Validation Item	Input Value	XML Value	Status		
Workcenter Plant Reference mismatch	002	01	Mismatch		
Workcenter Production Area Reference m	i s/h atch	002	Mismatch		

Twisted Wires Validation Results

FAILURE: Mismatches found between SBOM and Excel

Mismatch Details:

- * Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

Wire Length Validation Results

FAILURE: Wire length mismatches found

Wire Length Mismatch Details:

* Wire length mismatch for 53(1): XML=66666.0, Excel=1215.0

Validation Summary					
Validation Category	Issues Found	Status			
Work Center Attributes	2	FAIL			

Twisted Wires Validation	12	FAIL
Wire Length Validation	1	FAIL
OVERALL VALIDATION STATUS	15	FAIL

This is an automatically generated validation report For any discrepancies, please contact the validation team