## **SBOM VALIDATION REPORT**

### **Validation Parameters**

Workcenter Plant Reference:	002
Workcenter Production Area Reference:	02
Workcenter Use Single Final Assembly:	Yes

Report generated on: 2025-05-24 20:51:56

Work Center Validation Results					
Validation Item	Input Value	XML Value	Status		
Workcenter Plant Reference mismatch	002	01	Mismatch		
Workcenter Production Area Reference m	i <b>s</b> 2atch	002	Mismatch		

## **Twisted Wires Validation Results**

**FAILURE: Mismatches found between SBOM and Excel** 

#### **Mismatch Details:**

- \* Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- \* Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- \* Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- \* Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

# Wire Length Validation Results

SUCCESS: All wire lengths matched between SBOM and Excel

Validation Summary				
Validation Category	Issues Found	Status		
Work Center Attributes	2	FAIL		
Twisted Wires Validation	12	FAIL		
Wire Length Validation	0	PASS		
OVERALL VALIDATION STATUS	14	FAIL		

This is an automatically generated validation report For any discrepancies, please contact the validation team