SBOM VALIDATION REPORT

Validation Parameters

Workcenter Plant Reference:	001
Workcenter Production Area Reference:	001
Workcenter Use Single Final Assembly:	Yes

Report generated on: 2025-06-09 18:24:23

Work Center Validation Results					
Validation Item	Input Value	XML Value	Status		
Workcenter Plant Reference mismatch	001	01	Mismatch		
Workcenter Production Area Reference m	is001atch	002	Mismatch		

Twisted Wires Validation Results

FAILURE: Mismatches found between SBOM and Excel

Mismatch Details:

- * Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- * Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- * Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- * Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

Wire Length Validation Results

FAILURE: Wire length mismatches found

Wire Length Mismatch Details:

- * Wire length mismatch for 45(2): XML=687.0, Excel=707.0
- * Wire length mismatch for 44(1): XML=1215.0, Excel=115.0

Validation Summary		
Validation Category	Issues Found	Status

Work Center Attributes	2	FAIL
Twisted Wires Validation	12	FAIL
Wire Length Validation	2	FAIL
OVERALL VALIDATION STATUS	16	FAIL

This is an automatically generated validation report For any discrepancies, please contact the validation team