# **SBOM Validation Report**

#### **Validation Parameters**

Workcenter Plant Reference (Input): 002

Workcenter Production Area Reference (Input): 02 Workcenter Use Single File Assembly (Input): Yes

Report generated on: 2025-05-24 20:06:01

## **Work Center Validation Results**

- Workcenter Plant Reference mismatch: Input=002, XML=01
- Workcenter Production Area Reference mismatch: Input=02, XML=002

## **Twisted Wires Validation Results**

FAILURE: Mismatches found between SBOM and Excel

#### **Mismatch Details:**

- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

### **Summary:**

- Work Center validation issues: 2
- Twisted wire mismatches: 12
- Total issues: 14