SBOM Validation Report

Validation Parameters

Workcenter Plant Reference (Input): 002

Workcenter Production Area Reference (Input): 002 Workcenter Use Single File Assembly (Input): Yes

Report generated on: 2025-05-24 19:26:05

Work Center Validation Results

- Error validating work center attributes: name '_parse_xml' is not defined

Twisted Wires Validation Results

FAILURE: Mismatches found between SBOM and Excel

Mismatch Details:

- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

Summary:

- Work Center validation issues: 1
- Twisted wire mismatches: 12
- Total issues: 13