SBOM Validation Report

Validation Parameters

Workcenter Plant Reference (Input): 002

Workcenter Production Area Reference (Input): 02 Workcenter Use Single File Assembly (Input): No

Report generated on: 2025-05-24 19:57:48

Work Center Validation Results

- Workcenter Plant Reference missing in XML
- Workcenter Production Area Reference missing in XML
- Workcenter Use Single Final Assembly missing in XML

Twisted Wires Validation Results

FAILURE: Mismatches found between SBOM and Excel

Mismatch Details:

- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 41(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 41(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 41(1): SBOM=745.0, Excel=545.0
- Pitch mismatch for 51(1): SBOM=25.0, Excel=20.0
- Open end Length 1 (Untwist A) mismatch for 51(1): SBOM=55.0, Excel=50.0
- Length of twist mismatch for 51(1): SBOM=745.0, Excel=545.0

Summary:

- Work Center validation issues: 3
- Twisted wire mismatches: 12
- Total issues: 15