



			nic			
ALVOP	func]	AlV@pention	Tel .		ALVO	P
00	xxxq	alo		addi _	P. Alexander	09
al	xaxq	all	1, 19/k	SIti ->		10
10	xaaq	111		dr ->		00
U	and	aac (and source and	
	Sub.	a H		Jal ->		00
· ·	set	111				



Inst	Opcode	Function	
add	000000	000001	
sub 000000		000010	
and 000000		000100	
or	000000	001000	
slt	000000	010000	
addi	000001	-	
slti	000010	-	
lw	000011	-	
sw	000100	-	
peq 000101		-	
000110		-	
000111		1-	
jal	001000	-	



```
0) addi R1, R0, 1
   4) lw R10, 1000 (R0)
   8) addi R8, R0, 0
   12) addi R12, R0, 0
   16) aw R8, 2004 (R0)
 6 20) lw R9, 1000 (R12)
                                                                                             // for loop begins
   24) slt R11, R9, R10
8 28)beq R11, R1, 2
9 32)add R10, R9, R0
10 36)sw R8, 2004(R0)
                                                                                             // if R9 < R10
                            11 40) addi R12, R12, 4
   44) addi R8, R8, 1
13 48) slti R11, R8, 20
14 52) beq R11, R1, -9
15 56) sw R10, 2000(R0)
                                                                                             // for ends
16
```