

# 

### Power Supply Adaptar +5V




# Load Cell Sensor for weight measurement


### SF-400 >>> 1g-10kg




LCD(2\*16) Display Feed Weight



## Keypad for entering the weight that you need





# Warning of the end of the filling process

