

AUDIT REPORT

ORGANISATION INFORMATION																					
Auditee or client:	Altair Engineering Inspection Pte Ltd																				
Address:	#05-109, 18 Boon Lay Way, Tradehub 21, Singapore, 609966																				
Audit Location:	As above																				
Main contact name / position:	Mr. Shaik Khaja Mohiuddin & Mr. Siraj Masroor																				
e-mail:	khaja@altairengg.com																				
Telephone :	+65 (0) 64650877																				
Audit date(s):	10 th June 2026																				
Time spent onsite (in days):	1 day																				
Time spent on preparation and reporting (in days, not including post audit closures):	1 day																				
Audit Scope (see CP14 §4.6; 4.9; 4.11; 4.12):	☐ ISO9001 ☐ PCN24/CP08 ATO ☐ CP08/CM ATO ☐ CP08/ENG ☒ PCN24/CP09 AQB ☐ CP09/ENG ☐ Outside Agency ☐ Inside Agency ☐ Other (State below)																				
Audit type: (see CP14 §4.6; 4.9; 4.11; 4.12):	2 nd Surveillance																				
NDT Methods & Levels applicable:	<table border="1"> <thead> <tr> <th>Method</th> <th>Levels</th> </tr> </thead> <tbody> <tr> <td>MT Welds</td> <td>1 & 2</td> </tr> <tr> <td>PT Welds</td> <td>1 & 2</td> </tr> <tr> <td>RI Welds (Dense)</td> <td>2</td> </tr> <tr> <td>UT Welds 3.1/3.2/3.8/3.9)</td> <td>1 & 2</td> </tr> <tr> <td>TOFD Welds</td> <td>1 & 2</td> </tr> <tr> <td>UTPA (Multi)</td> <td>1 & 2</td> </tr> <tr> <td>UT Welds</td> <td>3</td> </tr> <tr> <td>UTPA Multi</td> <td>3</td> </tr> <tr> <td>TOFD Welds</td> <td>3</td> </tr> </tbody> </table>	Method	Levels	MT Welds	1 & 2	PT Welds	1 & 2	RI Welds (Dense)	2	UT Welds 3.1/3.2/3.8/3.9)	1 & 2	TOFD Welds	1 & 2	UTPA (Multi)	1 & 2	UT Welds	3	UTPA Multi	3	TOFD Welds	3
Method	Levels																				
MT Welds	1 & 2																				
PT Welds	1 & 2																				
RI Welds (Dense)	2																				
UT Welds 3.1/3.2/3.8/3.9)	1 & 2																				
TOFD Welds	1 & 2																				
UTPA (Multi)	1 & 2																				
UT Welds	3																				
UTPA Multi	3																				
TOFD Welds	3																				
Current Certification (including Expiry date):	AQB Authorisation with Expiry 11 th September 2027 Exam staff approval document 1069 dated 21 st May 2026																				
Lead Auditor (Name):	Mr. Jason Scott (On Site)																				
Appointed Support Assessors:	None																				
Appointed Observers:	None																				
Name / position of senior auditee representative(s) present at opening meeting:	1. Sirajul Hameed Masroor – Training Co-ordinator 2. Khaja - CEO 3. Amir Hamzah - Quality Coordinator 4. Siti - Admin Coordinator																				
Guide(s) (CP14 §4.6.2) assigned at opening meeting:	Amir Hamzah																				
Existing approvals held by auditee (with expiry dates):	See above																				
Name / position of senior auditee representative(s) present at closing meeting:	1. Sirajul Hameed Masroor – Training Co-ordinator 2. Khaja - CEO																				
Number of findings recorded:	09																				
Number of nonconformities recorded:	04																				

AUDIT REPORT

Number of observations recorded:	05
Whether senior representative of auditee accepts audit findings: Yes / No If no, summarise unresolved issues:	Yes
Latest Date for submission of cause analysis and proposed improvement action(s):	10 th July 2026
Latest date for submission of agreed improvement actions:	10 th September 2026
Lead assessor's view of auditee management's commitment to quality objectives (CP14 §4.6.6):	The senior management were in attendance throughout the audit and demonstrated a commitment to ensuring the BINDT / Altair Engineering Quality Objectives and requirements are met
Summary of audit and outcomes (CP14 §4.6.5):	This was a 2nd Surveillance audit that was conducted on-site by the lead auditor. The audit was successful and a lot of prior communication and request for supporting documentation was instrumental to the time management of the audit. There are 09 entries in the report, 04 of which are findings. The findings / non-compliance raised at this assessment are summarised below. • There are concerns raised over the awareness of change in updated documents • The organisation has applied for an extension to scope but the master reports for RI and UT Thickness are not yet in place • There are concerns on the calibration of equipment and authenticity of a calibration report • Some of the exam files reviewed exceeded the 28-day results notice issue requirement The organisation cooperated and communicated very openly and effectively in both the audit preparation and actual conduct of the remote assessment. All of the audit objectives were completed in the allocated time frame, and audit conclusions were able to be drawn.
Lead assessor's recommendation to BINDT (CP14 §4.6.7):	Conditional continued approval provided corrective actions to clear non-compliances are satisfactorily implemented within an agreed period. Evidence of implementation may be submitted to the Lead Auditor by e-mail Note: The audit recommends the next assessment to be in June 2027