

Security Audit Report

Generated on May 22, 2026 · 07:13

6	0	3	0	12
Devices	High Risk	Medium	Safe	Vulnerabilities

The audit scanned 6 devices on the target network. 0 high-risk and 3 medium-risk devices were identified, with 12 vulnerabilities catalogued. High-risk devices require immediate remediation.

Discovered Devices Inventory

IP / MAC	Hostname	Protocol	Open Ports	Risk	Score
ZB:00:11:22:33:44:55 00:11:22:33:44:55	Zigbee Bulb	Zigbee	—	CRITICAL	75.0
ZB:AA:BB:CC:DD:EE:FF AA:BB:CC:DD:EE:FF	Zigbee Sensor	Zigbee	—	CRITICAL	75.0
ZB:11:22:33:44:55:66 11:22:33:44:55:66	Smart Plug	Zigbee	—	CRITICAL	75.0
THREAD:FD00::1 Unknown	Google Nest Hub	Thread	—	MEDIUM	15.0
THREAD:FD00::2 Unknown	Apple HomePod Mini	Thread	—	MEDIUM	15.0
THREAD:FD00::3 Unknown	Smart Lock	Thread	—	MEDIUM	15.0

Vulnerability Analysis & Remediation

ZB:00:11:22:33:44:55 · *Zigbee Bulb*

● **HIGH** ZIGBEE_DEFAULT_KEY

Using default TC Link key (0x00...00) — Easily exploitable

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **CRITICAL** ZIGBEE_NO_ENCRYPT

Zigbee network is unencrypted — Packets are visible to everyone

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **MEDIUM** ZIGBEE_REPLAY

No protection against Replay attacks on the network

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

ZB:AA:BB:CC:DD:EE:FF · *Zigbee Sensor*

● **HIGH** ZIGBEE_DEFAULT_KEY

Using default TC Link key (0x00...00) — Easily exploitable

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **CRITICAL** ZIGBEE_NO_ENCRYPT

Zigbee network is unencrypted — Packets are visible to everyone

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **MEDIUM** ZIGBEE_REPLAY

No protection against Replay attacks on the network

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

ZB:11:22:33:44:55:66 · *Smart Plug*

● **HIGH** ZIGBEE_DEFAULT_KEY

Using default TC Link key (0x00...00) — Easily exploitable

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **CRITICAL** ZIGBEE_NO_ENCRYPT

Zigbee network is unencrypted — Packets are visible to everyone

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

● **MEDIUM** ZIGBEE_REPLAY

No protection against Replay attacks on the network

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

THREAD:FD00::1 · *Google Nest Hub*

● **MEDIUM** THREAD_ACTIVE_COMMISSIONER

Active commissioner mode enabled (potential attack vector)

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

THREAD:FD00::2 · *Apple HomePod Mini*

● **MEDIUM** THREAD_ACTIVE_COMMISSIONER

Active commissioner mode enabled (potential attack vector)

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

THREAD:FD00::3 · *Smart Lock*

● **MEDIUM** THREAD_ACTIVE_COMMISSIONER

Active commissioner mode enabled (potential attack vector)

Remediation: Apply latest firmware/patches and restrict service exposure with firewall rules.

This report is generated automatically by Pentex One. Findings should be validated by a qualified security professional before remediation.