

Pentex One — Security Audit Report

Generated on: May 13, 2026 - 04:21:37

Executive Summary

The security audit discovered a total of **7** devices. Among these, **0** were identified as high risk and **0** as medium risk. Immediate action is recommended for devices marked in red.

Discovered Devices Inventory

IP/MAC	Hostname	Protocol	Risk Level	Score
192.168.1.1 24:58:6E:9D:E4:EC	192.168.1.1	Wi-Fi	CRITICAL	100.0
192.168.1.2 Unknown	malak	Wi-Fi	CRITICAL	95.0
192.168.1.3 2C:16:BD:B4:BC:63	192.168.1.3	Wi-Fi	CRITICAL	95.0
192.168.1.6 0E:7F:C2:21:92:FD	poco-x7-pro	Wi-Fi	CRITICAL	95.0
192.168.1.8 1E:D0:8E:D4:03:66	realme-c53	Wi-Fi	CRITICAL	95.0
192.168.1.4 86:30:3E:4E:01:56	xiaomi-12t	Wi-Fi	SAFE	0.0
192.168.1.5 E6:E3:BB:D2:56:17	mohamed-kareem	Wi-Fi	SAFE	0.0

Vulnerability Analysis & Remediation

Device: 192.168.1.1 (192.168.1.1)

- **http-vuln-cve2014-3704** (MEDIUM)
Issue: ERROR: Script execution failed (use -d to debug)
Remediation: Contact vendor for updates.
- **TELNET_CLEARTEXT** (CRITICAL)
Issue: Telnet transmits all data including credentials in plaintext. This is a critical vulnerability.
Remediation: Disable the service and use encrypted alternatives (SSH/SFTP).
- **WEAK_TLS_SUPPORT** (MEDIUM)
Issue: TLS service detected. Older TLS 1.0/1.1 protocols may be enabled, which are deprecated and insecure.
Remediation: Contact vendor for updates.
- **DEFAULT_CREDENTIALS** (CRITICAL)
Issue: Default credentials 'root/root' work on the device!
Remediation: Change default passwords immediately to a strong, unique passphrase.

Device: 192.168.1.2 (malak)

- **TELNET_CLEARTEXT** (CRITICAL)

Issue: Telnet transmits all data including credentials in plaintext. This is a critical vulnerability.

Remediation: Disable the service and use encrypted alternatives (SSH/SFTP).

- **RPC_PORTMAPPER** (HIGH)

Issue: RPC portmapper is exposed. Allows enumeration of RPC services and can lead to NFS exploitation.

Remediation: Contact vendor for updates.

- **NETBIOS_EXPOSED** (HIGH)

Issue: NetBIOS session service exposed. Enables network share enumeration and potential pass-the-hash attacks.

Remediation: Contact vendor for updates.

- **AFP_EXPOSED** (MEDIUM)

Issue: Apple Filing Protocol exposed. AFP has known authentication weaknesses.

Remediation: Contact vendor for updates.

- **SMTP_SUBMISSION** (LOW)

Issue: SMTP submission port exposed. Ensure STARTTLS is enforced and authentication is required.

Remediation: Contact vendor for updates.

- **SOCKS_PROXY** (HIGH)

Issue: SOCKS proxy exposed. Can be abused for anonymous tunneling and bypassing network controls.

Remediation: Contact vendor for updates.

- **PPTP_VPN_WEAK** (HIGH)

Issue: PPTP VPN uses MS-CHAPv2, which is cryptographically broken and susceptible to offline brute-force.

Remediation: Contact vendor for updates.

- **MYSQL_EXPOSED** (CRITICAL)

Issue: MySQL database exposed to the network. Risk of unauthorized access, data exfiltration, and SQL injection.

Remediation: Contact vendor for updates.

- **RDP_EXPOSED** (HIGH)

Issue: RDP exposed. Prime target for brute-force, BlueKeep (CVE-2019-0708) and ransomware lateral movement.

Remediation: Contact vendor for updates.

- **VNC_EXPOSED** (CRITICAL)

Issue: VNC remote desktop exposed. Often runs without authentication or with weak passwords.

Remediation: Contact vendor for updates.

- **HTTP_ALT_EXPOSED** (MEDIUM)

Issue: Alternative HTTP port exposed. May expose admin panels, dev servers, or staging environments.

Remediation: Contact vendor for updates.

- **HTTPS_ALT_EXPOSED** (MEDIUM)

Issue: Alternative HTTPS port exposed. Verify TLS configuration and restrict admin access.

Remediation: Contact vendor for updates.

Device: 192.168.1.3 (192.168.1.3)

- **WEAK_TLS_SUPPORT** (MEDIUM)

Issue: TLS service detected. Older TLS 1.0/1.1 protocols may be enabled, which are deprecated and insecure.

Remediation: Contact vendor for updates.

- **RTSP_STREAM_EXPOSED** (HIGH)

Issue: RTSP stream exposed. Camera/media streams accessible without authentication.

Remediation: Contact vendor for updates.

- **RSYNC_EXPOSED** (HIGH)

Issue: rsync port exposed. Can allow unauthorized data access or manipulation without authentication.

Remediation: Contact vendor for updates.

- **MSSQL_EXPOSED** (CRITICAL)

Issue: Microsoft SQL Server exposed to network. Risk of SQL injection, data exfiltration, and remote code execution.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_1795** (LOW)

Issue: Non-standard service on port 1795 (proprietary-daemon v3.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **VNC_EXPOSED** (CRITICAL)

Issue: VNC remote desktop exposed. Often runs without authentication or with weak passwords.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_6847** (LOW)

Issue: Non-standard service on port 6847 (proprietary-daemon v3.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_7834** (LOW)

Issue: Non-standard service on port 7834 (embedded-server 473). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_10032** (LOW)

Issue: Non-standard service on port 10032 (unknown-service/3.5.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_15812** (LOW)

Issue: Non-standard service on port 15812 (embedded-server 343). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_16355** (LOW)

Issue: Non-standard service on port 16355 (embedded-server 823). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_16983** (LOW)

Issue: Non-standard service on port 16983 (unknown-service/1.3.4). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_18493** (LOW)

Issue: Non-standard service on port 18493 (unknown-service/1.11.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_24097** (LOW)

Issue: Non-standard service on port 24097 (embedded-server 530). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_25775** (LOW)

Issue: Non-standard service on port 25775 (proprietary-daemon v3.3). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_28486** (LOW)

Issue: Non-standard service on port 28486 (unknown-service/2.16.3). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_35831** (LOW)

Issue: Non-standard service on port 35831 (unknown-service/1.5.0). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_41353** (LOW)

Issue: Non-standard service on port 41353 (embedded-server 930). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

• **UNKNOWN_PORT_43336** (LOW)

Issue: Non-standard service on port 43336 (unknown-service/5.14.1). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_44297** (LOW)

Issue: Non-standard service on port 44297 (unknown-service/2.0.0). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_45942** (LOW)

Issue: Non-standard service on port 45942 (proprietary-daemon v2.1). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_46256** (LOW)

Issue: Non-standard service on port 46256 (unknown-service/1.3.4). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_47059** (LOW)

Issue: Non-standard service on port 47059 (proprietary-daemon v3.0). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_49004** (LOW)

Issue: Non-standard service on port 49004 (unknown-service/2.2.0). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_50794** (LOW)

Issue: Non-standard service on port 50794 (embedded-server 957). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_51096** (LOW)

Issue: Non-standard service on port 51096 (proprietary-daemon v3.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_53940** (LOW)

Issue: Non-standard service on port 53940 (unknown-service/4.0.2). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_54068** (LOW)

Issue: Non-standard service on port 54068 (proprietary-daemon v2.4). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_64028** (LOW)

Issue: Non-standard service on port 64028 (proprietary-daemon v2.6). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

Device: 192.168.1.6 (poco-x7-pro)

- **FTP_CLEARTEXT** (HIGH)

Issue: FTP transmits credentials in cleartext. Packet capture trivially reveals usernames and passwords.

Remediation: Disable the service and use encrypted alternatives (SSH/SFTP).

- **DNS_AMPLIFICATION** (MEDIUM)

Issue: Open DNS resolver detected. Can be exploited for DNS amplification DDoS attacks.

Remediation: Contact vendor for updates.

- **HTTP_UNENCRYPTED** (MEDIUM)

Issue: Unencrypted HTTP traffic exposes data to man-in-the-middle attacks.

Remediation: Contact vendor for updates.

- **RPC_PORTMAPPER (HIGH)**

Issue: RPC portmapper is exposed. Allows enumeration of RPC services and can lead to NFS exploitation.

Remediation: Contact vendor for updates.

- **MSRPC_EXPOSED (HIGH)**

Issue: Microsoft RPC endpoint mapper exposed. Used in DCOM attacks and lateral movement.

Remediation: Contact vendor for updates.

- **NETBIOS_EXPOSED (HIGH)**

Issue: NetBIOS session service exposed. Enables network share enumeration and potential pass-the-hash attacks.

Remediation: Contact vendor for updates.

- **SMB_EXPOSED (CRITICAL)**

Issue: SMB exposed. Vulnerable to EternalBlue (MS17-010) and related ransomware attacks.

Remediation: Contact vendor for updates.

- **SYSLOG_EXPOSED (MEDIUM)**

Issue: Syslog port exposed without authentication. Logs can be forged or intercepted.

Remediation: Contact vendor for updates.

- **IPP_EXPOSED (MEDIUM)**

Issue: IPP (Internet Printing Protocol) exposed. Can allow unauthorized printing or information disclosure.

Remediation: Contact vendor for updates.

- **MSSQL_EXPOSED (CRITICAL)**

Issue: Microsoft SQL Server exposed to network. Risk of SQL injection, data exfiltration, and remote code execution.

Remediation: Contact vendor for updates.

- **VNC_EXPOSED (CRITICAL)**

Issue: VNC remote desktop exposed. Often runs without authentication or with weak passwords.

Remediation: Contact vendor for updates.

- **HTTP_ALT_EXPOSED (MEDIUM)**

Issue: Alternative HTTP port exposed. May expose admin panels, dev servers, or staging environments.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_8646 (LOW)**

Issue: Non-standard service on port 8646 (proprietary-daemon v3.5). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_15881 (LOW)**

Issue: Non-standard service on port 15881 (proprietary-daemon v3.9). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_18981 (LOW)**

Issue: Non-standard service on port 18981 (embedded-server 314). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_21326 (LOW)**

Issue: Non-standard service on port 21326 (embedded-server 661). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_54217 (LOW)**

Issue: Non-standard service on port 54217 (embedded-server 768). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_61645 (LOW)**

Issue: Non-standard service on port 61645 (unknown-service/5.7.5). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

Device: 192.168.1.8 (realme-c53)

- **DNS_AMPLIFICATION** (MEDIUM)

Issue: Open DNS resolver detected. Can be exploited for DNS amplification DDoS attacks.

Remediation: Contact vendor for updates.

- **RPC_PORTMAPPER** (HIGH)

Issue: RPC portmapper is exposed. Allows enumeration of RPC services and can lead to NFS exploitation.

Remediation: Contact vendor for updates.

- **IMAP_CLEARTEXT** (MEDIUM)

Issue: IMAP without TLS exposes email metadata and credentials.

Remediation: Contact vendor for updates.

- **IMAPS_TLS_VERIFY** (LOW)

Issue: IMAPS service detected. Ensure TLS certificate is valid and strong ciphers are in use.

Remediation: Contact vendor for updates.

- **PPTP_VPN_WEAK** (HIGH)

Issue: PPTP VPN uses MS-CHAPv2, which is cryptographically broken and susceptible to offline brute-force.

Remediation: Contact vendor for updates.

- **MYSQL_EXPOSED** (CRITICAL)

Issue: MySQL database exposed to the network. Risk of unauthorized access, data exfiltration, and SQL injection.

Remediation: Contact vendor for updates.

- **VNC_EXPOSED** (CRITICAL)

Issue: VNC remote desktop exposed. Often runs without authentication or with weak passwords.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_34577** (LOW)

Issue: Non-standard service on port 34577 (proprietary-daemon v3.6). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_45302** (LOW)

Issue: Non-standard service on port 45302 (unknown-service/1.20.4). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_46348** (LOW)

Issue: Non-standard service on port 46348 (proprietary-daemon v2.9). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_52798** (LOW)

Issue: Non-standard service on port 52798 (embedded-server 139). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

- **UNKNOWN_PORT_64308** (LOW)

Issue: Non-standard service on port 64308 (unknown-service/2.20.1). Unknown services should be reviewed and closed if not needed.

Remediation: Contact vendor for updates.

Access Control (RFID/NFC) Audit

UID / Identifier	Tag Technology	Risk Rating
52:47:71:A1	Mifare Classic 4K	RISK
79:A1:A6:E5:26:F1:78	HID iCLASS	RISK
5B:34:08:18:D4:1A:2A	MIFARE DESFire EV2	RISK
38:C4:06:0A	Mifare Classic 4K	RISK
56:2E:28:83:84:7D:73	Mifare Classic 4K	RISK

07:5C:0F:46:DB:9F:56	MIFARE DESFire EV2	RISK
85:E2:1B:B9:0E:13:F2	HID iCLASS	RISK
04:8D:DE:06:57:FD:F0	Mifare Classic 4K	RISK
0F:0B:9A:83:BE:B9:17	NFC NTAG216	SAFE
6C:01:A2:1B:F9:FD:69	NFC NTAG216	SAFE
B4:36:20:76:41:12:63	NFC NTAG213	SAFE
A3:FD:EE:D4:15:92:75	NFC NTAG216	SAFE
C8:20:4D:B8:EA:59:D3	EM4100	RISK