


- Pole foundation -02 No
- -01 10-Phase Plate
- 01 No. Danger Plate
- Eye balt
- 11KV Disc Insultor 6 No.
- 11KV Pin Insulator/ Pilot Insulator 03 No Mis. Channel [50x50 y 6mi
- Binding wire -01 No.


- Stay Complete 02 No-
- * Foundation 02 No.
- forcrossarm & smild Steel Channel -01
 - * Different size New Bolt 2kg
 - x Jumber wire 2 kg.

× 3m long

for cross Bracing. 02 No



- * लम्बी म.ग. Line में प्रत्येक 1 mile (1610 m) दूरी के पश्चात् स्वक H- Pole (Not Pole mountains) का प्रयोग किया
- अने Not pole mounting type H-Pole ही प्राहित है।
- * म उत्मेक H type Pole की Earthing आवश्यक होती है।



O Rail Pole 11.5m long -	2.M.
	2Mo.
3) Pole foundation -	-2 No
(3) Stay Complete -	-2No.
(S) M.S. Channel (100 x 50 x 10 mm x 2.65 m long) - 1 No.	
6) Now balt for difference size -	
T.P.M.O Set Complete -	- 1 No-
@ Disc Insulator (11)KU with Althing - 3No.	
(9) Jumper wire	
10 Fuse set complete -	1 No.
1 mrs. channel (100x50 x 10mm) x 2 m dong) - 1 no.	
@ 11 KV Pin 9msulator = 31	
(3) Transformer 1 V.4 KV, 50 H2	
(9) Dropper gron (.75×75×8mm	x2mlog) -1
(5) W.I. (Wrough Iron Clamp).	_ 2No-
(6) Phose Plate -	- 1 No Junil
@ Barbed wire -	- 5 kg M
(8) Danger Plata	1 No.
19 Earthing Complete .	- 1 No.
2 2 ye balt	INO.
@ Painting of Pole	- 1 No.