Uniform Residential Appraisal Report

123 FALLING TREE CT, TREEVILLE, VA 12345

SUMMARY

Opinion of Market Value	$491,000
Effective Date of Appraisal	09/20/2019
Assignment Reason	Purchase
Borrower Name	Betty Borrower | Bob Borrower
Current Owner of Public Record	Betty Borrower | Bob Borrower | Jane Doe
Contract Price	$489,000.00
Listing Status	Pending

Market Value Condition	Subject to Repair
Property Valuation Method	Traditional Appraisal
Appraiser Name	Agatha Appraiser

Property Description

Construction Method	Site Built
Attachment Type	Detached
Planned Unit Development (PUD)	Yes ☑ No ☐
Condominium	Yes ☐ No ☑
Cooperative	Yes ☐ No ☑
Condop	Yes ☐ No ☑
Subject Site Owned in Common	Yes ☐ No ☑
Units Excluding ADUs	1
Property Rights Appraised	Fee Simple
Is the highest and best use of the subject property as improved (or as proposed per plans and specifications) the present use?	Yes ☑ No ☐
Zoning Compliance	Legal

Overall Quality	Q4
Overall Condition	C4

Apparent Defects, Damages, Deficiencies Requiring Action

Description
Carpet is stained in one corner of the Dining Room.

Location	Section of Roof
Estimated Cost to Repair	$1,500
Location	Dining Room
Feature	Flooring
Affects Soundness or Structural Integrity	No
Recommended Action	None
Feature	Driveway
Feature	Fence | Deck | Porch | Indoor Fireplace | Media Room | Wet Bar
Total Cost	$1,500
As Is Overall Condition Rating	C5

Total Estimated Cost of Items Recommended for Repair	$1,500

Assignment Information

Assignment Reason	Purchase
Borrower Name	Betty Borrower | Bob Borrower
Seller Name	Jane Doe
Current Owner of Public Record	Betty Borrower | Bob Borrower | Jane Doe

Property Valuation Method	Traditional Appraisal
Was a Property Data Report used in lieu of an Inspection?	Yes ☐ No ☑

Contact Information

Client/Lender	Lender
Client/Client	Client

Contact Information - Client/[Party Role Type]

Company Name	DEF Bank | XYZ Appraisal Management Company

Contact Information - Appraiser

Name	Agatha Appraiser
Designation	SRA
Inspection Date	09/20/2019

Level	Certified Residential
ID	XYZ12345
State	VA
Expires	10/10/2020

Contact Information - Significant Real Property Appraisal Assistance

Name	Andrew Appraiser

ID	XYZ12345
State	VA
Expires	10/10/2020

Subject Property

Physical Address	123 Falling Tree Ct Treeville 12345 VA
County	Arboreal
Neighborhood Name	Sunnyside

Attachment Type	Detached
Units Excluding ADUs	1
Accessory Dwelling Units	0
Dwellings Containing Units	1
Special Tax Assessments	No

Planned Unit Development (PUD)	Yes ☑	No ☐
Condominium	Yes ☐	No ☑
Cooperative	Yes ☐	No ☑
Condop	Yes ☐	No ☑
Property on Native American Lands	Yes ☐	No ☑
Subject Site Owned in Common	Yes ☐	No ☑
Homeowner Responsible for all Exterior Maintenance of Dwelling(s)	Yes ☑	No ☐
New Construction	Yes ☐	No ☑

Ownership Rights

Property Rights Appraised	Fee Simple
All Rights Included in Appraisal	Yes

Site

Total Site Size	14,950.000
Number of Parcels	1

APN Description
Land with Dwelling

Assessor Parcel Number (APN)	1234-56-7891-000
Parcel Size	14,950.000
Compliance	Legal
Classification Code	R10

Classification Code Description
Residential - 10 Dwelling Units per Acre

Street Access and Surface	Asphalt Local Road
Primary Access	Public Street
Typical for Market	Yes ☑ No ☐

Site Influence

Influence	Residential

Comment
Typical residential subdivision

Site Influence Commentary

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Proximity	Bordering
Impact	Neutral

View and Impact to Value / Marketability

View Commentary

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

(Primary)	(Primary) Residential
Range of View	Full
Impact	Neutral

Site Features and Impact to Value / Marketability

Detail	No Hazard Zone Noted
Detail	Topography | Rolling

Comment

Steep grade is less marketable.

Impact	Adverse

Utilities and Impact to Value / Marketability

Broadband Internet Available	**Yes** ☑ **No** ☐
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public
Public/Private	Public | Public | Public | Public

Apparent Defects, Damages, Deficiencies (Site)

Location	Section of Roof

Site Valuation Methodology

Address	123 Falling Tree Ct Treeville 12345 VA	**County**	Arboreal
		Data Source	Physical Measurement
Assessor Parcel Number (APN)	1234-56-7891-000	**Site Size**	14,950.000

Site Commentary

Site Commentary
On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Disaster Mitigation

Mitigation Feature	None

Energy Efficient and Green Features

Known Renewable Energy Components	**Yes** ☐	**No** ☑
Known Building Certifications	**Yes** ☐	**No** ☑
Green / Energy Efficiency Rating Organization	RESNET	
Rating	HERS	
Score	62	

Energy Efficient and Green Features Impact to Value / Marketability

Impact to Value / Marketability	Neutral

Sketch

Measurement Standard	ANSI

Dwelling Exterior

Subject Property Units in Structure	1
Dwelling Style	Colonial
Front Door Elevation	3-4 Ft.
Year Built	2004
Construction Method	Site Built
Converted Area and Similarity to Rest of Living Area	None

Quality and Condition

Exterior Quality Rating	Q4	**Exterior Condition Rating**	C4
Detail	Vinyl		

Quality and Condition - Condition Status

Exterior Walls and Trim	Typical Wear and Tear

Condition Comment
Minor cracks to vinyl typical for age.

Detail	Poured Concrete | Basement
Foundation	Typical Wear and Tear
Detail	Composition
Roof	Typical Wear and Tear

Condition Comment
Reported condition is subject to repair; see defects table and commentary below.

Quality Comment
Double Thermal Pane contributes to Energy Efficiency.

Windows	Typical Wear and Tear

Condition Comment
Windows same age as house.

Feature	Exterior Walls and Trim
Other (Describe)	Typical Wear and Tear

Mechanical System Details

System	Forced Warm Air		
Detail	Natural Gas	**Core Heating System Below Grade**	Yes
System	Centralized		
		Other Mechanical Systems	Sump Pump

Apparent Defects, Damages, Deficiencies (Dwelling Exterior - [Structure Identifier])

Description
Roof is significantly worn and has damaged flashing, but no apparent active leaks.

Feature	Roof	**Location**	Section of Roof
Affects Soundness or Structural Integrity	Yes	**Recommended Action**	Repair

Unit Interior

Finished Above Grade	3,002
Finished Above Grade (Nonstandard)	0
Unfinished Above Grade	0
Finished Below Grade	1,300
Finished Below Grade (Nonstandard)	0
Unfinished Below Grade	230
Area Data Source	Physical Measurement
Below Grade Finish Compared to Above	Similar
ADU	No
Data Source	Physical Measurement

Levels in Unit	3
Occupancy	Owner
Total Bedrooms	5

Total Bathrooms

Full	3
Half	1
Level in Unit	Level B1
Grade Level Detail	Interior and Exterior Access Walk Out Partially Below Grade
Area	1,300 230
Room Summary	Bath - Half

Quality and Condition

Interior Quality Rating	Q4	**Interior Condition Rating**	C4
Room	Level B1 Bath - Half		

Quality Comment
Ceramic flooring.

Condition Comment
Half bath newer than rest of house.

Update Status	Fully Updated
Time Frame	5-10 years
Condition Status	Typical Wear and Tear
Overall Update Status for Bathrooms	Moderately Updated
Feature	Flooring

Quality Comment
Throughout all bedrooms and living areas.

Condition Comment
Original carpet, stained in one corner in the Dining Room.

Detail	Carpet | 8 Ft. | Cathedral
Condition Status	Damaged and Functional
Overall Update Status for Flooring	Not Updated

Accessibility Features for Individuals with Disabilities

Comment
The shower has been modified.

Feature	Shower

Apparent Defects, Damages, Deficiencies (Unit Interior - [Outbuilding Type] - [Structure Identifier] - [Unit Identifier])

Description
Roof is significantly worn and has damaged flashing, but no apparent active leaks.

Unit Interior *(continued)*

Feature	Roof
Location	Section of Roof
Affects Soundness or Structural Integrity	Yes
Recommended Action	Repair

Functional Obsolescence

Functional Issues	None

Outbuilding

[Outbuilding Type] - {No Subsection}

Units in Structure	1

[Outbuilding Type] - Mechanical System Details

System	Forced Warm Air
Detail	Natural Gas
System	Centralized

Other Mechanical Systems	Sump Pump

[Outbuilding Type] - Apparent Defects, Damages, Deficiencies ([Outbuilding Type])

Description
Roof is significantly worn and has damaged flashing, but no apparent active leaks.

Feature	Roof
Location	Section of Roof
Affects Soundness or Structural Integrity	Yes
Recommended Action	Repair

Vehicle Storage

Storage	Driveway
Number of Parking Spaces	2
Detail	Asphalt
Storage	Garage

Apparent Defects, Damages, Deficiencies (Vehicle Storage)

Feature	Driveway
Location	Section of Roof

Subject Property Amenities

Amenity Category	Outdoor Accessories | Outdoor Living | Whole Home | Miscellaneous
Subject Property Amenity	Fence | Deck | Porch | Indoor Fireplace | Media Room | Wet Bar
Material	Wood | Concrete
Detail	400 | 351 | 1

Apparent Defects, Damages, Deficiencies (Subject Property Amenities)

Feature	Fence | Deck | Porch | Indoor Fireplace | Media Room | Wet Bar
Location	Section of Roof

Subject Property Amenities Commentary

Amenities Commentary
On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Overall Quality and Condition

Overall Quality	Q4	**Overall Condition**	C4

Exterior Condition

{Structure Identifier}	C4

Interior Condition

{Unit Identifier}	C4

Highest and Best Use

Legally Permissible	Yes ☑	No ☐	**Financially Feasible**	Yes ☑ No ☐
Physically Possible	Yes ☑	No ☐	**Maximally Productive**	Yes ☑ No ☐
Is the highest and best use of the subject property as improved (or as proposed per plans and specifications) the present use?	Yes ☑	No ☐		

Market

Market Area Boundary

North: E. Grant Highway, South: E. Temple Ave., East: Chicken Rd., West: 10 Main Ave.

Search Criteria Description

Search Criteria limited by Detached units with a lot size of up to .6 acres and Finished Above Grade Area between 2700 and 3300 sq. ft. Additional factors include between 2-4 full bathrooms, 3-5 bedrooms, a basement and a 2 car garage. Searched between closing dates of 9/30/2017 and 9/30/2019.

Search Result Metrics

Active Listings	2	**Lowest Sale Price**	$400,000.00
Median Days on Market	11	**Median Sale Price**	$499,000.00
Lowest List Price	$435,000.00	**Highest Sale Price**	$597,000.00
Median List Price	$440,000.00	**Distressed Market Competition**	Yes ☐ No ☑
Highest List Price	$445,000.00		
Pending Sales	1		
Sales in Past ___ Months	24		
Sales in Past ___ Months	35		

Housing Trends

Demand/Supply	Shortage	**Marketing Time**	Under 3 months

Project Information

Planned Unit Development (PUD)	Yes ☑ No ☐
Condominium	Yes ☐ No ☑
Cooperative	Yes ☐ No ☑
Condop	Yes ☐ No ☑
Project Information Data Source	Physical Measurement
Monthly Amount	$34
Common Amenities / Services Included	Trash Removal
Utilities Included	None

Project Factors and Impact to Value / Marketability

Detail	Yes ☐ No ☑
Detail	Yes ☐ No ☑
Detail	$34
Detail	None

Project Factors Commentary

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Detail	None

Project Information Commentary

Project Information Commentary

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Subject Listing Information

Data Source	Physical Measurement
Listing Status	Pending
Listing Type	MLS
Listing ID	FQ999999
Start Date	09/05/2019
End Date	09/17/2019
DOM	13
Starting List Price	$489,000.00
Current or Final List Price	$489,000.00
Total DOM	13

Analysis of Subject Property Listing History

The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis.

Sales Contract

Is there a sales contract?	Yes	**Contract Price**	$489,000.00
Was sales contract information analyzed?	Yes	**Contract Date**	09/17/2019
Does this appear to be an arm's length transaction?	Yes	**Transfer Terms**	Typically Motivated
		Personal Property Conveyed	Yes

Financial Sales Concessions

Total Sales Concessions	$5,000.00
Typical for Market	Yes

Prior Sale and Transfer History

Subject Transfer History

Prior Sales or Transfers **Yes** ☐ **No** ☑

Analysis of Prior Sale and Transfer History of Subject Property

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Data Source	Physical Measurement
Data Source	Real Estate Agent

Comparable Transfer History

Transfer Terms	None

Analysis of Prior Sale and Transfer History of Comparable Sales

On average, homes with a HERS Index rating of 62 are 38% more energy efficient than a standard new house. | Despite lack of supply, homes are not going up in value due to seasonality. This is typical for 3rd quarter, evidenced by the fact that there are only 2 active listings, which have less finished area than the subject and not indicative of prices decreasing. | $5,000 concession towards repair of the carpet. Window treatments, washer and dryer, and media room projector conveyed per sales contract. | The only listing of the subject property in the past year has been for $489,000 for 13 days prior to contract. The contract provided to the appraiser contains no atypical terms or conditions, see Sales Contract section for further analysis. | The highest and best use analysis as improved is physically possible and legally permissible based on its current zoning. Analysis of the market shown below demonstrates that the existing structure as a single family residence is its financially feasible and maximally productive use. | The Overall Quality and Condition matches the Interior Quality and Condition, as well as the Exterior Quality and Condition, since the exterior and interior are both of the same age. | Only prior sale of the subject was when it was a new construction in 2004. | Prior sale of comp 1 was a typically motivated arms-length transaction.

Data Source	Physical Measurement

Sales Comparison Approach

General Information

Property Address	123 Falling Tree Ct Treeville 12345 VA
List Price	$489,000.00
Listing Status	Pending
Contract Price	$489,000.00

Financial Sales Concessions

Sales Concessions	$5,000.00
Contract Date	09/17/2019
Days on Market	13
Attached/Detached	Detached
Property Rights Appraised	Fee Simple
Native American Lands	No
All Rights Included	Yes
Property Address	123 Falling Tree Ct Treeville 12345 VA
Data Source	Physical Measurement
Attached/Detached	Detached
Property Rights Appraised	Fee Simple
Native American Lands	No

Project Information

Monthly Fee	$34
Common Amenities/Services	Trash Removal
Common Amenities/Services	Trash Removal
Special Assessments	None
Site Owned in Common	**Yes** ☐ **No** ☑

Site

Site Size	14,950.000
Neighborhood Name	Sunnyside
Zoning Compliance	Legal
Hazard Zone	No Hazard Zone Noted
Primary Access	Public Street
Street Type | Surface	Asphalt Local Road
Topography	Rolling
Site Characteristics	Topography
Site Influence (Location)	Residential
View | Range	Full Residential
Site Owned in Common	**Yes** ☐ **No** ☑
Site Size	14,950.000
Neighborhood Name	Sunnyside
Zoning Compliance	Legal
Primary Access	Public Street

Dwelling(s)

Year Built	2004
Construction Method	Site Built
Dwelling Style	Colonial
Functional Issues	None
Disaster Mitigation	None

Sales Comparison Approach *(continued)*

Heating	Natural Gas Forced Warm Air
Cooling	Centralized

Energy Efficient and Green Features

Renewable Energy Component	None
Building Certification	None
Efficiency Rating	HERS 62

Unit(s)

Location of ADU	Dwelling
Levels in Unit	3
Bedrooms	5

Unit(s) - Baths

Full | Half	3 1
Finished Area Above Grade	3,002
Finished Area Above Grade (Nonstandard)	0
Unfinished Area Above Grade	0
Finished Area Below Grade	1,300
Finished Area Below Grade (Nonstandard)	0
Unfinished Area Below Grade	230
Features for Individuals w/Disabilities	Shower

Exterior Quality and Condition

Quality	Q4
Exterior Walls and Trim	Vinyl
Foundation	Basement
Roof	Composition
Condition	C4

Exterior Quality and Condition - Condition Status

Exterior Walls and Trim	Typical Wear and Tear
Foundation	Typical Wear and Tear

Quality and Condition

Roof	Typical Wear and Tear
Windows	Typical Wear and Tear
Other (Describe)	Typical Wear and Tear
Exterior Walls and Trim	Typical Wear and Tear
Foundation	Typical Wear and Tear
Roof	Typical Wear and Tear
Windows	Typical Wear and Tear
Other (Describe)	Typical Wear and Tear

Interior Quality and Condition

Quality	Q4
Condition	C4

ADU Interior Quality and Condition

Location of ADU	Dwelling
Quality	Q4
Condition	C4

Overall Quality and Condition

Quality	Q4
Condition	C4
Quality	Q4
Condition	C4

Property Amenities

{Amenity Category}	Fence
Outdoor Living	Deck | Porch
{Amenity Category}	1 Indoor Fireplace
{Amenity Category}	Media Room | Wet Bar

Sales Comparison Approach *(continued)*

{Amenity Category}	Deck | Porch
{Amenity Category}	1 Indoor Fireplace
{Amenity Category}	Media Room | Wet Bar

Vehicle Storage

Type | Spaces | Detail	Driveway Asphalt 2
Type | Spaces | Detail	460 Built-in Garage 2

Outbuilding

Heating	Forced Warm Air
Cooling	Centralized

Summary

List Price	$489,000.00 Pending
Contract Price	$489,000.00
Indicated Value	$491,000

Additional Properties Analyzed Not Used

Property Address	123 Falling Tree Ct Treeville 12345 VA
Status	Pending

	Subject Property	Comparable #1		Comparable #2		Comparable #3	
General Information							
Comparable #	—	1		2		3	
Property Address	123 Falling Tree Ct Treeville 12345 VA	241 Rapid Creek Ln Treeville 12345 VA		188 Fallen Oak Ct Treeville 12345 VA		210 Cannon Ball Rd Treeville 12345 VA	
Data Source	—	—		—		—	
Proximity to Subject	—	N 0.17		N 0.06		NE 0.40	
List Price	$489,000.00	$460,000.00		$449,900.00		$525,000.00	
Listing Status	Pending	Settled Sale		Settled Sale		Settled Sale	
Sale Price	—	$460,000.00 | $430,000.00		$450,000.00		$520,000.00	
Transfer Terms	—	Typically Motivated | Typically Motivated		Typically Motivated		Typically Motivated	
Sales Concessions	$5,000.00	$8,500.00	$0	$11,000.00	$0	$10,400.00	$0
Contract Date	—	07/22/2019	$0	08/05/2019	$0	07/02/2019	$0
Sale Date	—	08/17/2019 | 09/01/2018	$0	09/10/2019	$0	08/31/2019	$0
Days on Market	13	12		6		14	
Attached/Detached	Detached	Detached		Detached		Detached	
Property Rights Appraised	Fee Simple	Fee Simple		Fee Simple		Fee Simple	
Native American Lands	No	—		—		—	
All Rights Included	Yes	—		—		—	
[Additional Row]	—	—	$2,000	—	$2,000	—	
Project Information							
Monthly Fee	$34	—		—		—	
Common Amenities/Services	Trash Removal	—		—		—	
Site							
Site Owned in Common	No	No		No		No	
Site Size	14,950.000	17,886.000	$0	13,038.000	$0	16,039.000	$0
Neighborhood Name	Sunnyside	Sunnyside		Sunnyside		Hilldale	$0
Zoning Compliance	Legal	—		—		—	
Hazard Zone	No Hazard Zone Noted	No Hazard Zone Noted		No Hazard Zone Noted		No Hazard Zone Noted	
Primary Access	Public Street	—		—		—	
Street Type | Surface	Asphalt Local Road	—		—		—	
Topography	Rolling	Rolling		Rolling		Flat	-$2,000
Site Characteristics	Topography	Topography		Topography		Topography	
Site Influence (Location)	Residential	Residential		Busy Roadway	$5,000	Residential	

	Subject Property	Comparable #1		Comparable #2		Comparable #3	
View | Range	Full Residential	Full Residential		Full Residential		Full Residential	
[Additional Row]	—	—	$2,000	—	$2,000	—	
Dwelling(s)							
Year Built	2004	2004		2004		2001	$0
Construction Method	Site Built	Site Built		Site Built		Site Built	
Dwelling Style	Colonial	Colonial		Colonial		Colonial	
Functional Issues	None	—		—		—	
Disaster Mitigation	None	—		—		—	
Heating	Natural Gas Forced Warm Air	Natural Gas Forced Warm Air		Natural Gas Forced Warm Air		Natural Gas Forced Warm Air	
Cooling	Centralized	Centralized		Centralized		Centralized	
[Additional Row]	—	—	$2,000	—	$2,000	—	
Energy Efficient and Green Features							
Renewable Energy Component	None	—		—		—	
Building Certification	None	—		—		—	
Efficiency Rating	HERS 62	None		HERS 61		None	
Unit(s)							
Location of ADU	Dwelling	Dwelling		Dwelling		Dwelling	
Levels in Unit	3	—		—		—	
Bedrooms	5	4	$10,000	4	$10,000	4	$10,000
Baths – Full | Half	3 1	2 1	$10,000	2 2	$5,000	3 1	
Finished Area Above Grade	3,002	3,260	-$10,300	2,804	$7,900	2,816	$7,400
Finished Area Above Grade (Nonstandard)	0	—		—		—	
Unfinished Area Above Grade	0	—		—		—	
Finished Area Below Grade	1,300	0	$26,000	1,200	$2,000	1,328	$0
Finished Area Below Grade (Nonstandard)	0	—		—		—	
Unfinished Area Below Grade	230	1,624	-$13,940	66	$1,640	148	$0
Features for Individuals w/ Disabilities	Shower	—		—		—	
[Additional Row]	—	—	$2,000	—	$2,000	—	
Exterior Quality and Condition							
Quality	Q4	Q4		Q4		Q4	
Exterior Walls and Trim	Vinyl	Vinyl		Vinyl		Vinyl	
Foundation	Basement	—		—		—	
Roof	Composition	Composition		Composition		Composition	
Condition	C4	C4		C4		C4	
Exterior Walls and Trim	Typical Wear and Tear	—		—		—	
Foundation	Typical Wear and Tear	—		—		—	
Roof	Typical Wear and Tear	—		—		—	
Windows	Typical Wear and Tear	—		—		—	
Interior Quality and Condition							
Quality	Q4	Q4		Q4		Q4	
Condition	C4	C4		C4		C4	
Kitchen	Fully Updated	Partially Updated		Not Updated		Not Updated	
Overall Bathrooms	Moderately Updated	—		—		—	
Overall Flooring	Not Updated	Not Updated		Not Updated		Not Updated	
ADU Interior Quality and Condition							
Location of ADU	Dwelling	Dwelling		Dwelling		Dwelling	
Quality	Q4	Q4		Q4		Q4	
Condition	C4	C4		C4		C4	
Kitchen	Fully Updated	Partially Updated		Not Updated		Not Updated	
Overall Bathrooms	Moderately Updated	—		—		—	
Overall Flooring	Not Updated	Not Updated		Not Updated		Not Updated	
Overall Quality and Condition (Ratings: 1-6, 1 is highest)							
Quality	Q4	Q4		Q4		Q4	

	Subject Property	Comparable #1		Comparable #2		Comparable #3	
Condition	C4	C4	-$5,000	C4	-$1,000	C4	-$1,000
Property Amenities							
Outdoor Accessories	Fence	—		—		—	
Outdoor Living	Deck | Porch	Patio | Deck	$6,000	Patio | Porch	$2,000	Deck | Patio	$6,000
Water Features	—	—		—		Inground Pool	-$12,000
Whole Home	1 Indoor Fireplace	—		—		—	
Miscellaneous	Media Room | Wet Bar	—	$6,000	—	$6,000	—	$6,000
Vehicle Storage							
Type| Spaces | Detail	Driveway Asphalt 2	Driveway Asphalt 2		Driveway Asphalt 2		Driveway Asphalt 2	
Outbuilding (ADU and vehicle storage are not included in Finished Area, Unfinished Area, or room counts)							
Heating	Forced Warm Air	—		—		—	
Cooling	Centralized	—		—		—	
Summary							
List Price	$489,000.00 Pending	$460,000.00		$449,900.00		$525,000.00	
Sale Price	—	$460,000.00 | $430,000.00		$450,000.00		$520,000.00	
Net Adjustment Total	—	$30,760		$40,540		$14,400	
Price Per Finished Area Above Grade	—	$141		$160		$185	
Adjusted Price	—	$490,760.00		$490,540.00		$534,400.00	
Comparable Weight	—	Most		Most		Less	

Rental Information

Rent Schedule

Occupancy	Owner

Comparable Rental Properties

Subject Property	123 Falling Tree Ct Treeville 12345 VA
Data Source	Physical Measurement

Comparable Rental Analysis

Neighborhood Name	Sunnyside
Project Common Amenities / Services	Trash Removal
Site Influence	Residential
Site Size	14,950.000
Interior Condition	C4
Bedrooms	5

Comparable Rental Analysis - Baths

Full |Half	3 1
Neighborhood Name	Sunnyside
Site Size	14,950.000

Income Approach

Gross Rent Multiplier Comparables

Property Address	123 Falling Tree Ct Treeville 12345 VA
Units Excluding ADUs	1
Accessory Dwelling Units	0
Property Address	123 Falling Tree Ct Treeville 12345 VA
Data Source	Physical Measurement
Units Excluding ADUs	1
Accessory Dwelling Units	0

Cost Approach

Site Value

Address	123 Falling Tree Ct Treeville 12345 VA

SiteValue

County	Arboreal

Land Comparables

Data Source	Physical Measurement
Assessor Parcel Number (APN)	1234-56-7891-000
Site Size	14,950.000

General Description

Cost Data Source	Physical Measurement

Reconciliation

Approaches to Value

Indicated Value	$491,000

Reason for Exclusion
Not Necessary for Credible Results

Appraisal Summary

Contract Price	$489,000.00
Opinion of Market Value	$491,000
Market Value Condition	Subject to Repair

Reasonable Exposure Time	90 0
Effective Date of Appraisal	09/20/2019

Apparent Defects, Damages, Deficiencies

Description
Carpet is stained in one corner of the Dining Room.

Location	Section of Roof
Estimated Cost to Repair	$1,500
Location	Dining Room
Feature	Flooring
Affects Soundness or Structural Integrity	No
Recommended Action	None
Feature	Driveway
Feature	Fence | Deck | Porch | Indoor Fireplace | Media Room | Wet Bar
Total Cost	$1,500
As Is Overall Condition Rating	C5

Total Estimated Cost of Items Recommended for Repair	$1,500

Certifications

Signature

Level	Certified Residential
ID	XYZ12345
State	VA
Expires	10/10/2020