

a Complete command record
Rotor 1
Rotor 2
Rotor 3
Rotor 4
Command (rad/s)
100
0
−100
0
10
20
30
40
50
Trajectory time (s)
b Steady-window commands
Command (rad/s)
50
0
30
35
40
45
50
55
Trajectory time (s)