■■■■ ■■■■■ • GOVERNMENT OF INDIA

■■ ■■■■■ ■■■■■■■■ • MINISTRY OF JAL SHAKTI

■■■■■■■■■ ■■■■ ■■■■■■■ ■■■■■■■■■■ • NATIONAL DAM SAFETY AUTHORITY

# STATUTORY DAM SAFETY INSPECTION & CONDITION REPORT

**File Ref: F.No. NDSA/CWC/2026/INSP/AUDIT-0842 | Verification Code:**
**REP-HV-BHK-TEST-1791218347-20261005_163911**

**OFFICIAL STATUTORY RECORD** **DAM SAFETY ACT 2021 COMPLIANT** **SCAN QR TO VERIFY AUTHENTICITY**

| | | | |
|---|---|---|---|
| **Dam Name:** | Bhakra Hydro Project | **Dam Asset Code:** | BHK-TEST-1791218347 |
| **Location & State:** | Bilaspur, Himachal Pradesh | **Structural Type:** | Concrete Gravity |
| **Height & Coordinates:** | 226.0 m (31.41° N, 76.43° E) | **Issuing Department:** | National Dam Safety Authority (NDSA) |
| **Inspecting Body:** | Hydroelectric Structural Inspection Cell | **Audit Timestamp:** | 05 October 2026, 16:39 UTC |

## 1. STRUCTURAL ANOMALY & DEFECT ASSESSMENT SUMMARY

| | | | | |
|---|---|---|---|---|
| DEF-177-277 | CRACK | **DefectSeverity.HIGH** | 65.5 mm | WORK_ORDER_CREATED |

## 2. RECORDED INSPECTIONS & FIELD VISITS HISTORY

| Insp Code | Type & Date | Inspector / Department | Status |
|---|---|---|---|
| INSP-BHK-TEST-1791218347-20261005163911 | **DRONE_VISUAL** 2026-10-05 | Hydroelectric Structural Inspection Cell | **InspectionStatus.COMPLETED** |

## 3. SANCTIONED WORKS & MAINTENANCE HISTORY

| | | | |
|---|---|---|---|
| WO-2026-039 | **Inject polyurethane resin & epoxy seal** | Priority: **HIGH** | **MaintenanceStatus.OPEN** |

**Prepared By:**
Senior Inspection Engineer
*Hydroelectric Inspection Cell*

**Reviewed By:**
Executive Engineer
*Dam Safety Organisation (SDSO)*

**Approved By Authority:**
Chief Engineer (Dam Safety)
*Ministry of Jal Shakti / CWC*

GOVT OF INDIA
NDSA • CWC
STATUTORY AUDIT
OFFICIAL SEAL