



































Resist Strip After Etch

- Subsequent to etch, photoresist used as mask (if at all) should be removed
- · The resist hardens during exposure to plasma
 - Due to temperature increase, chemical or physical transformation in the resist
 - Chemical and physical transformation of the resist due to interaction with plasma
- Oxygen plasma treatment to burn the resist: CO and CO₂ are produced
- · Wet chemical etch
 - H₂SO₄:H₂O₂ etch (piranha clean or SPM)
 - NH₄OH:H₂O₂:H₂O etch (APM)
- Usually a combination of dry strip (O₂ plasma) and wet strip are used.

2023 Monsoon

EE669: Etching: Anil Kottantharayil

19

