



Inspection Report

Project: Monster Cub Painting and Fabric Doping

Course/Section: BAMT 302

Date of Inspection: 07/13/26

Location: Main Campus

Purpose of Inspection

To assess the current condition of the Monster Cub aircraft in preparation for painting and fabric doping as part of the BAMT 302 restoration project.

Inspection Findings

- The aircraft is in a partially disassembled condition.
- The wings are not installed.
- Several exterior panels are missing.
- Existing paint surfaces show signs of wear and require proper surface preparation before repainting.
- The aircraft surfaces require cleaning and preparation before the application of fabric dope and paint.
- Areas to be painted and doped should be free from dirt, grease, and loose materials before work begins.

Overall Assessment

The aircraft is suitable for the planned painting and fabric doping activities after proper surface preparation. Missing components, including the wings and several exterior panels, are outside the scope of this project.

Recommendations

1. Clean and prepare all surfaces before painting and doping.
2. Ensure proper surface preparation to achieve good paint and dope adhesion.
3. Protect surrounding areas and components during the painting process.
4. Apply paint and fabric dope according to the approved project procedures.



DPR AVIATION COLLEGE

☎ 0923 921 6062

📍 Lumang Bayan, Plaridel, Bulacan

✉ inquiry@dpr-pats.edu.ph

