

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

TASK CARD #1 (Monster Cub)

AIRCRAFT FABRIC DOPING

I. General Information

The Monster Cub aircraft uses a fabric-covered airframe on selected flight control surfaces and structural components. Fabric doping is the process of applying aircraft dope to the fabric covering to tighten, seal, and protect the fabric from moisture, fuel, oil, ultraviolet (UV) radiation, and environmental damage. Proper doping also provides a smooth surface for primer and paint application while maintaining the aircraft's aerodynamic efficiency. All work shall be performed in accordance with approved aircraft maintenance procedures, manufacturer's recommendations, and under the supervision of the project instructor.

Required no. of Work Hours : 120 to 135 Total hrs
Required no. of Personnel : 8 to 10 / Day

II. Task Objective

- 1.) To prepare the aircraft fabric surface by cleaning and inspecting it before dope application.
- 2.) To apply aircraft dope uniformly in accordance with approved aircraft maintenance practices.
- 3.) To ensure the fabric covering is properly sealed, tightened, protected, and ready for primer and paint application.

Warning:

- AN OPERATING PROCEDURE, PRACTICE, OR CONDITION WHICH, IF NOT CORRECTLY FOLLOWED, COULD RESULT IN SERIOUS PERSONAL INJURY OR LOSS OF LIFE.
- Aircraft dope and thinner are highly flammable.
- Wear appropriate PPE including respirator, gloves, and safety goggles.
- Perform all work in a well-ventilated area away from open flames and sparks.

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

Cautions:

- Use only approved aircraft fabric doping materials.
- Do not apply excessive coats that may increase fabric weight.
- Observe the manufacturer's drying time between coats.
- Avoid contamination from dust, moisture, or oil during application.

III. Equipment and Materials Required

Note: When more than one tool part number is listed under the same "reference" number, the tools shown are alternates to each other within the same airplane series. Tool part numbers that are replaced or non-procurable are preceded by "Opt", which stands for optional.

1. Tools & Equipment

• 1 set -	Complete PPE / uniform (Hard hat, Reflector Vest, Gloves, Earplugs)
• 1 set -	Basic Set of Tools (Flat head screw, Cross point screw, Combination Pliers Diagonal Cutting Pliers, Combination Wrench, Ball Peen Hammer)
• 1 pc -	HVLP Spray Gun or Natural Bristle Brush
• 1 pc -	Air Compressor
• 1 pc -	Mixing Container
• 1 pc -	Stirring Stick
• 1 pc -	Sanding Block
• 1 pc -	Flashlight / Inspection Light

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

2. Materials and Consumables

- | | |
|--------|----------------------------------|
| • pcs. | Aircraft Nitrate Dope |
| • pcs. | Aircraft Butyrate Dope |
| • pack | Approved Dope Thinner |
| • pcs. | Tack Cloth |
| • pcs. | Lint-Free Cleaning Cloth |
| • pcs. | Masking Tape |
| • pcs. | Fine Sandpaper (320–400 grit) |
| • pcs. | Approved Aircraft Fabric Cleaner |

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

IV. Procedures

Fabric Doping	Date:	Performed by:	Checked by:	Remarks:
1. Secure the aircraft and prepare the work area with adequate ventilation.				
2. Inspect the fabric covering for tears, loose stitching, wrinkles, or contamination.				
3. Clean the fabric surface using an approved cleaner and allow it to dry completely./				
4. Mask adjacent areas to prevent overspray or contamination.				
5) Mix the aircraft dope and thinner according to the manufacturer's instructions.				
6). Apply the first coat evenly using an approved spray gun or brush.				
7) Allow the dope to dry completely before applying the next coat.				
8) Lightly sand the surface if required and remove dust with a tack cloth.				
9) Apply additional coats as specified until the required finish is achieved.				
10) Perform a final inspection for uniform coverage, proper adhesion, and surface finish. Clean the work area and record the completed maintenance task.				

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

V. Illustrated Reference



VI. List of applicable references

- FAA Advisory Circular AC 43.13-1B & 43.13-2B – Acceptable Methods, Techniques, and Practices – Aircraft Inspection and Repair
- Poly-Fiber Aircraft Covering Manual
- CC11-160 Aircraft Maintenance Manual

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01



DPR - PHILIPPINE ACADEMY IN TECHNOLOGY & SCIENCES
Aircraft Maintenance Technology Dept.
 DPR-PATS Hangar, Plaridel Airport, Bulacan 3004 Philippines www.dpr-pats.edu.ph
 CAAP ATOC # 21-86

INSPECTION TAG

Part # : _____ Serial # : _____

Item Description/Ident : _____

Installed / Removed from which aircraft? _____ Date : _____

Make and Model : _____ Reg. # : _____

Inspector: _____ Lic. #: _____ Sign. _____

Recommendation:

☐ **REPAIRABLE**

☐ **SERVICEABLE**

☐ **REJECTED**

Prepared by:

MR. JOEL ANDREI VIDAD
 Project Manager

MR. MARK JAMES B. ENRIQUEZ
 Engineering and Planning Department

Evaluated and Approved by:

MR. ELCEL INGENTE/ MR. DARYL ELONA/
MR. JOHN RICK ANTHONY PUNGILAN
 Project Manager

ENGR. RUTH RUCHELL DC. RELLEJA
/ ENGR. AILLEYS MONDE MAE CENTENO
 Engineering and Planning Department

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 07/14/2026 Revised: 00

**MR. ROLANDO MAGTALAS / MR.
JOHN KEVIN AJOSE**
Safety Department

**MR. CARMELO PIO
OCAMPO / CAPT. JAMES
DANIEL SANTOS**
Quality Department

MS. FRANZELLE M. MENDOZA
Engineering and Planning Department

Noted by:

MR. REUEL DE CASTRO
Maintenance and Engineering
Operations Manager