

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

TASK CARD #1 (Monster Cub)

AIRCRAFT PAINTING

I. General Information

The Monster Cub aircraft utilizes a fabric-covered airframe on selected flight control surfaces and structural components. After the fabric doping process has been completed and properly cured, aircraft painting is performed to provide long-term protection against ultraviolet (UV) radiation, moisture, fuel, oil, chemicals, and environmental damage. The paint system also enhances the aircraft's appearance while maintaining the durability and aerodynamic smoothness of the fabric surface. All painting work shall be performed in accordance with approved aircraft maintenance procedures, manufacturer's recommendations, and under the supervision of the project instructor.

Required no. of Work Hours : 120 to 135 Total hrs
Required no. of Personnel : 8 to 10 / Day

II. Task Objective

- 1.) To prepare the doped fabric surface for aircraft paint application.
- 2.) To apply aircraft primer and finish coat uniformly in accordance with approved aircraft maintenance practices.
- 3.) To ensure the painted surface provides maximum protection, durability, and an acceptable aircraft finish..

Warning:

- **AN OPERATING PROCEDURE, PRACTICE, OR CONDITION WHICH, IF NOT CORRECTLY FOLLOWED, COULD RESULT IN SERIOUS PERSONAL INJURY OR LOSS OF LIFE.**
- **Aircraft paint, reducer, and hardener are highly flammable.**
- **Wear appropriate PPE including respirator, gloves, and safety goggles.**
- **Perform all work in a well-ventilated area away from open flames and sparks.**

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

Cautions:

- Use only approved aircraft paint systems compatible with the fabric covering.
- Do not apply excessive paint thickness that may increase aircraft weight.
- Observe the manufacturer's flash-off and curing times between coats.
- Prevent dust, moisture, insects, and contaminants from contacting the painted surface during curing.

III. Equipment and Materials Required

Note: When more than one tool part number is listed under the same "reference" number, the tools shown are alternates to each other within the same airplane series. Tool part numbers that are replaced or non-procurable are preceded by "Opt", which stands for optional.

1. Tools & Equipment

• 1 set -	Complete PPE / uniform (Hard hat, Reflector Vest, Gloves, Earplugs)
• 1 set -	Basic Set of Tools
• 1 pc -	HVLP Spray Gun or Natural Bristle Brush
• 1 pc -	Air Compressor
• 1 pc -	Mixing Container
• 1 pc -	Paint Mixing Container
• 1 pc -	Stirring Stick
• 1 pc -	Paint Strainer
• 1 pc -	Tack Cloth
• 1 pc -	Sanding Block
• 1 pc -	Flashlight / Inspection Light

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

2. Materials and Consumables

- | | |
|--------|-------------------------------------|
| • pcs. | Aircraft Polyurethane Primer |
| • pcs. | Aircraft Polyurethane Topcoat Paint |
| • pack | Approved Reducer/Thinner |
| • pcs. | Hardener/Catalyst |
| • pcs. | Lint-Free Cleaning Cloth |
| • pcs. | Masking Tape |
| • pcs. | Masking Paper |
| • pcs. | Fine Sandpaper (320–400 grit) |
| • pcs. | Wax and Grease Remover |
| • pcs. | Approved Aircraft Fabric Cleaner |

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

IV. Procedures

Fabric Doping	Date:	Performed by:	Checked by:	Remarks:
1. Secure the aircraft and prepare the painting area with adequate ventilation.				
2. Inspect the doped fabric surface for defects such as dust, pinholes, cracks, runs, or surface contamination.				
3. Lightly sand the surface if necessary and remove all sanding dust using a tack cloth.				
4. Clean the surface with an approved wax and grease remover.				
5) Mask all adjacent areas to prevent paint overspray.				
6). Mix the aircraft primer or paint with the approved reducer and hardener according to the manufacturer's instructions.				
7) Apply a light tack coat using an approved HVLP spray gun.				
8) Allow the recommended flash-off time before applying succeeding coats.				

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

9) Apply additional primer or finish coats evenly until the required coverage and finish are achieved.				
10) Allow the paint to cure completely according to the manufacturer's specifications.				
11) Perform a final inspection for uniform color, gloss, adhesion, complete coverage, and absence of defects such as runs, orange peel, or dry spray.				
12) Remove masking materials, clean the work area, and record the completed maintenance task.				

V. Illustrated Reference



VI. List of applicable references

- FAA Advisory Circular AC 43.13-1B & 43.13-2B – Acceptable Methods, Techniques, and Practices – Aircraft Inspection and Repair
- Poly-Fiber Aircraft Covering Manual
- CC11-160 Aircraft Maintenance Manual

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01



DPR - PHILIPPINE ACADEMY IN TECHNOLOGY & SCIENCES
Aircraft Maintenance Technology Dept.
 DPR-PATS Hangar, Plaridel Airport, Bulacan 3004 Philippines www.dpr-pats.edu.ph
 CAAP ATOC # 21-86

INSPECTION TAG

Part # : _____ Serial # : _____

Item Description/Ident : _____

Installed / Removed from which aircraft? _____ Date : _____

Make and Model : _____ Reg. # : _____

Inspector: _____ Lic. #: _____ Sign. _____

Recommendation:

☐ **REPAIRABLE**

☐ **SERVICEABLE**

☐ **REJECTED**

Prepared by:

MR. JOEL ANDREI VIDAD
 Project Manager

MR. MARK JAMES B. ENRIQUEZ
 Engineering and Planning Department

Evaluated and Approved by:

MR. ELCEL INGENTE/ MR. DARYL ELONA/ MR. JOHN RICK ANTHONY PUNGILAN
 Project Manager

ENGR. RUTH RUCHELL DC. RELLEJA / ENGR. AILLEYS MONDE MAE CENTENO
 Engineering and Planning Department

 DPR - AVIATION COLLEGE Plaridel Airport, Lumangbayan, Plaridel, Bulacan 3004 Philippines dpr-pats.edu.ph	Implementation by: Raymond Ramirez DPR AC AMT Head of Training
Aircraft Maintenance Technology CAAP ATOC #21-86	Issued: 08/24/2026 Revised: 01

**MR. ROLANDO MAGTALAS / MR.
JOHN KEVIN AJOSE**
Safety Department

**MR. CARMELO PIO
OCAMPO / CAPT. JAMES
DANIEL SANTOS**
Quality Department

MS. FRANZELLE M. MENDOZA
Engineering and Planning Department

Noted by:

MR. REUEL DE CASTRO
Maintenance and Engineering
Operations Manager