CS 350 Milestone Two - GPIO UART State Machine

The diagram matches the server logic: ON turns GPIO 18 on, OFF turns it off, EXIT or QUIT turns the LED off, cleans up GPIO, and ends the loop. Any other command is ignored.