

TODO

- Figure out wire harness
- Determine correct PU/PD polarity for R5 and R15
- Find proper connectors for J1 and J2