

Bellis Technology INTELLIGENCE IN VALIDATION 拜里斯科技(深圳)有限公司	文件编号	作业名称	工 程	项 目	BCV			作业序号
	WI SOP BCV PACKAGING-001	PACKAGING-1	Package	SHEET	1/4	Rev No.	1.0	1
※非相关工程人员严禁涂改图面资料或加注任何文字		修改确认: Denis	修改人:		确认人: 刘培 张凤云		制定人: Jack Xiang	

Operation Procedure

受控文件

1. Fold the inner box。 (PIC.1)
2. Put one interval board into the complete inner box。 (PIC.2)
3. First we need to fold the two types divided board and put into picture 2。 (PIC.3)
4. Material:

ITL Part	Description	Q'ty
Inner box 59-222412-01		1
interval board 59-222416-01		1
divided board 59-222414-01		4
divided board 59-222415-01		4

Quality inspection




- Self-inspection:
1. It's should not have wrinkle on the box。
2. box should not have damaged。
3. Partition board should follow standard put in box。

Tools



Fold the inner box

Put one interval board



Assemble the two types divided board and put it in inner box second

 Bellis Technology INTELLIGENCE IN VALIDATION 拜里斯科技(深圳)有限公司	文件编号	作业名称	工 程	项目	BCV			作业序号
	WI SOP BCV PACKAGING-001	PACKAGING-2	Package	SHEET	2/4	Rev No.	1.0	2
※非相关工程人员严禁涂改图面资料或加注任何文字		修改确认: Denis	修改人:		确认人: 刘培 张凤云		制定人: Jack Xiang	

受控文件

Operation Procedure

1. Take the product and put in box, one floor just can be put 6pcs.
2. Bottom have completed and then follow previous page to operate, and finally should be put the interval board in the top when all product completed page.

3. material:

ITL Part	Description	Q'ty
interval board 59-222416-01		1

Quality inspection




- Self-inspection:
- 1.appearance should not have wrinkle, damaged。

Tools



1

Put the product into box



2

Put the interval board in the top when all product completed page

 Bellis Technology INTELLIGENCE IN VALIDATION 拜里斯科技(深圳)有限公司	文件编号	作业名称	工 程	项 目	BCV			作业序号
	WI SOP BCV PACKAGING-001	PACKAGING-3	Package	SHEET	3/4	Rev No.	1.0	3
※非相关工程人员严禁涂改图面资料或加注任何文字		修改确认: Denis	修改人:		刘培 张凤云			制定人: Jack Xiang
				确认人:				

受控文件

Operation Procedure

- 1. To stick carton label in carton outward and bound carton by PET. (label should stick upward, PIC.1)
- 2. Put the bound carton on the pallet and it is should be put a price of PE sheet on the pallet before put the (carton label should be look and one floor just can be put 4 carton, PIC.2)
- 3. Material:


ITL Part	Description	Q'ty
Outer box 59-222413-01		1

Quality inspection



- 1. Label should stick upward on the outer box
- 2. PET cannot bound the special position

Tools



carton。

1



2

 Bellis Technology INTELLIGENCE IN VALIDATION 拜里斯科技(深圳)有限公司	文件编号	作业名称	工 程	项 目	BCV			作业序号
	WI SOP BCV PACKAGING-001	PACKAGING-4	Package	SHEET	4/4	Rev No.	1.0	4
※非相关工程人员严禁涂改图面资料或加注任何文字		修改确认: Denis	修改人:		确认人刘培 张凤云		制定人: Jack Xiang	

Operation Procedure

受控文件

1. Confirm the goods can be meet the order request.(PIC.1)
2. When the carton have completed the put and then put a price PE sheet and put 4 pcs paper cover , also put cover pallet on the top of carton. (PIC.2)
3. use tools to bound the PET for pallet goods.(PIC.3)
4. use Wrapping machine to bound all pallet.(PIC3.4.5)
after bound the PE sheet please notice to check whether tight.

注：料号及规格

Item	P/N	Description	Q' ty
1	Cover pallet 59-220840-01	1145*1145*113MM	1
2	PE sheet pallet cover PE film	1200*1000*0.08MM	1
3	Paper cover 59-220817	1450*50*50MM (air) 1750*50*50 (sea)	4



Quality inspection



- Self-inspection:
1. Confirm the carton should not miss to stick。
- Mutual-inspection:
1. Confirm the PET is tight。
 2. Confirm the PE sheet is tight。
 3. By air freight: pallet goods should not over 20 cartons
By sea : pallet goods should not over 24 cartons

Tools

Wrapping machine

