

COMMERCIAL INVOICE

1.Exporter

BYD AUTO INDUSTRY CO., LTD
NO.3001、3007,HENGPING ROAD,PINGSHAN,SHENZHEN, P.R.CHINA
TEL: +86-755-89888888
FAX: +86-755-28403950


2.Importer

Shlomo Motors Ltd.
Kiryat Shlomo, Nir Zevi, Israel, Zip Code: 72905
Contact Person: Lee Suisa
Tel: +972532724014

4.No.of Invoice	5.Date
BYDEUIL0001W2507011_36	2025/7/30
6.Transportation	7.Freight term
Air	EXW

3.Delivery to

Shlomo Motors Ltd.
Champion logistic warehouse, Kibbutz Givat Brenner 60948 Israel
Contact Person: Lee Suisa
Tel: +972532724014

8.Payment Terms

T/T

9.Place of loading	10.Place of delivery
HONGKONG,CHINA	ISRAEL

11.Marks & Numbers	12.order number	13.COUNTRY OF ORIGIN	14.CASE NAME	15.HU NO.	16.*CASE NO.	17.*SER.NO.	18.*SAP NO.	19.PART NO	20. Description of Goods	21.HS CODE	22.QTY (PIECE)	23. Unit Price (EUR)	24. Amount (EUR)
BYD	2903643	CHINA	BYDEUIL0001W2507011_36	SPX202507272442	1	1	15613867-00	SC2E-1703561	RND gear surface shell of LHD gearshift lever	8708299000	46	0.74	34.04
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280451	1	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280452	2	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280453	3	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280454	4	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	2903643	CHINA	BYDEUIL0001W2507011_39	SPS202507270031	1	1	13930767-00	EKEA-3402010A-D5AC	Steering wheel assembly - dark black 5+	8708949001	1	140.41	140.41
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280180	1	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	6	82.47	494.82
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280181	2	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	6	82.47	494.82
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280181	2	2	14639321-00	SC2EM-3602600B	Front mmWave radar	8512900000	3	90.71	272.13
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280182	3	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1	82.47	82.47
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280183	4	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1	82.47	82.47
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280184	5	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1	82.47	82.47
	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290210	1	1	17399652-00	\	SC2EAU-2142700_repair kit for power domain control unit	9032899080	1	1063.16	1063.16
	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290211	2	1	17399652-00	\	SC2EAU-2142700_repair kit for power domain control unit	9032899080	1	1063.16	1063.16
	3003600	CHINA	BYDEUIL0001W2507026_03	SP2202507272493	1	1	13451184-00	SC2EM-6205200	Rear left door lock body assembly	8301209000	3	12.18	36.54

	3003600	CHINA	BYDEUIL0001W2507026_04	SP2202507281602	1	1	13132985-00	EM2E-8107010	EM2E-8107010_Evaporator core assembly_M00666	8415909000	1	39.85	39.85
	3003600	CHINA	BYDEUIL0001W2507026_05	SP2202507281603	1	1	13222666-00	SC2E-5305040	Gearshift control mechanism cover assembly	8708299000	5	25.92	129.6
	3003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291446	1	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator upper	8708299000	1	11.6	11.6
	3003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291447	2	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator upper	8708299000	1	11.6	11.6
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292902	1	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292903	2	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292904	3	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292905	4	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292906	5	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
	2903642	CHINA	BYDEUIL0001W2507009_49	SW1202507292386	1	1	17122501-00	SA3HKU-6801120	Driver's power seat sliding rail assembly	9401999000	1	90.07	90.07
										88			5,287.84
SAY EUR FIVE THOUSAND TWO HUNDRED AND EIGHTY-SEVEN AND CENTS EIGHTY-FOUR (EUR 5287.84) ONLY.													

Packing List

1. Exporter

BYD AUTO INDUSTRY CO., LTD
NO.3001、3007,HENGPING ROAD,PINGSHAN,SHENZHEN, P.R.CHINA
TEL: +86-755-89888888
FAX: +86-755-28403950


2. Importer

Shlomo Motors Ltd.
Kiriat Shlomo, Nir Zevi, Israel, Zip Code: 72905
Contact Person: Lee Suisa
Tel: +972532724014

4. No. Of Invoice
BYDEUIL0001W2507011_3
6

5. Date
2025/7/30

6.ETD
2025/8/7

7. ETA
2025/8/7

3.Delivery to

Shlomo Motors Ltd.
Champion logistic warehouse, Kibbutz Givat Brenner 60948 Israel
Contact Person: Lee Suisa
Tel: +972532724014

8.Place of loading
HONGKONG,CHINA

9. Place of delivery
ISRAEL

10. Packing
PACKAGE

11. Transportation Method
Air

12. Freight Terms
EXW

13.Marks& Numbers	14.order number	15.COUNTRY OF ORIGIN	16.CASE NAME	17.HU NO.	18.*CASE NO.	19.*SER.N O.	20.*SAP NO.	21. PARTNAME (ENGLISH)	22.Description of Goods	23.HS CODE	23. N.W. (kgs)(TOTAL)	25. G.W. (kgs) (TOTAL)	26. Measurement (CBM) (TOTAL)	27.Quantity (PACKAGE)
BYD	2903643	CHINA	BYDEUIL0001W2507011_36	SPX20250727244 2	1	1	15613867-00	SC2E-1703561	RND gear surface shell of LHD gearshift lever	8708299000	0.138	0.400	0.024	1
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE20250728045 1	1	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	3.290	5.700	0.132	1
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE20250728045 2	2	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	3.290	5.700	0.132	1
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE20250728045 3	3	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	3.290	5.700	0.132	1
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE20250728045 4	4	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	3.290	5.700	0.132	1
2903643	CHINA	BYDEUIL0001W2507011_39	SPS20250727003 1	1	1	1	13930767-00	EKEA-3402010A-D5AC	Steering wheel assembly - dark black 5+	8708949001	1.510	2.300	0.031	1
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 0	1	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	8.664	16.300	0.296	1
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 1	2	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	8.664			
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 1	2	2	14639321-00	SC2EM-3602600B	Front mmWave radar	8512900000	0.231			
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 2	3	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1.444	2.100	0.031	1
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 3	4	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1.444	2.100	0.031	1
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS20250728018 4	5	1	13898219-00	EM2EU-3402010E-Y1H	Steering wheel assembly - gray	8708949001	1.444	2.100	0.031	1

	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290210	1	1	17399652-00	\	SC2EAU-2142700 repair kit for SC2EAU-2142700 repair kit for	9032899080	25.590	27.600	0.104	1
	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290211	2	1	17399652-00	\	SC2EAU-2142700 repair kit for	9032899080	25.590	27.600	0.104	1
	3003600	CHINA	BYDEUIL0001W2507026_03	SP2202507272493	1	1	13451184-00	SC2EM-6205200	Rear left door lock body assembly	8301209000	1.092	2.500	0.047	1
	3003600	CHINA	BYDEUIL0001W2507026_04	SP2202507281602	1	1	13132985-00	EM2E-8107010	EM2E-8107010 Evaporator	8415909000	1.230	2.000	0.034	1
	3003600	CHINA	BYDEUIL0001W2507026_05	SP2202507281603	1	1	13222666-00	SC2E-5305040	Gearshift control mechanism cover	8708299000	3.150	10.000	0.313	1
	3003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291446	1	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator	8708299000	0.641	1.100	0.021	1
	3003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291447	2	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator	8708299000	0.641	1.100	0.021	1
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292902	1	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	3.020	3.400	0.015	1
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292903	2	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	3.020	3.400	0.015	1
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292904	3	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	3.020	3.400	0.015	1
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292905	4	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	3.020	3.400	0.015	1
	3003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292906	5	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	3.020	3.400	0.015	1
	2903642	CHINA	BYDEUIL0001W2507009_49	SW1202507292386	1	1	17122501-00	SA3HKU-6801120	Driver's power seat sliding rail assembly	9401999000	4.825	7.200	0.095	1
											114.558	166.00	2.082	24

SAY TWENTY-FOUR (24) PACKAGES ONLY.