COMMERCIAL INVOICE

1.Exporter

BYD AUTO INDUSTRY CO., LTD NO.3001、3007,HENGPING ROAD,PINGSHAN,SHENZHEN, P.R.CHINA

TEL: +86-755-89888888 FAX: +86-755-28403950



2.Importer

Shlomo Motors Ltd. Kiriat Shlomo, Nir Zevi,Israel,Zip Code: 72905

Contact Person: Lee Suisa

Tel: +972532724014

4.No.of Invoice	5.Date
BYDEUIL0001W2507 011_36	2025/7/30
6.Transportation	7.Freight term
Air	EXW

10.Place of delivery

12.18

36.54

3.Delivery to

Shlomo Motors Ltd.

Champion logistic warehouse, Kibbutz Givat Brenner 60948 Israel

Contact Person: Lee Suisa Tel: +972532724014

3003600

CHINA

BYDEUIL0001W2507026 03

SP2202507272493

8.Payment Terms

9.Place of loading

T/T

Tel: +97253	Tol: +070522724044										HONGKONG,CHINA	ISRAEL	
11.Marks & Numbers	12.order number	13.COUNTR Y OF ORIGIN	14.CASE NAME	15.HU NO.	116.*CA SE NO.		18.*SAP NO.	19.PART NO	20. Description of Goods	21.HS CODE	22.QTY (PIECE)	23. Unit Price (EUR)	24. Amount (EUR)
BYD	2903643	CHINA	BYDEUIL0001W2507011_36	SPX202507272442	1	1	15613867-00	SC2E-1703561	RND gear surface shell of LHD gearshift lever	8708299000	46	0.74	34.04
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280451	1	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280452	2	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280453	3	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	3003600	CHINA	BYDEUIL0001W2507026_02	SPE202507280454	4	1	14740848-00	SA3HKU-4107300	Middle taillight	8512209000	1	241.87	241.87
	2903643	CHINA	BYDEUIL0001W2507011_39	SPS202507270031	1	1	13930767-00	EKEA-3402010A- D5AC	Steering wheel assembly - dark black 5+	8708949001	1	140.41	140.41
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280180	1	1	13898219-00	EM2EU-3402010E- V1H	Steering wheel assembly – gray	8708949001	6	82.47	494.82
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280181	2	1	13898219-00	EM2EU-3402010E- Y1H	Steering wheel assembly – gray	8708949001	6	82.47	494.82
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280181	2	2	14639321-00	SC2EM-3602600B	Front mmWave radar	8512900000	3	90.71	272.13
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280182	3	1	13898219-00	EM2EU-3402010E- Y1H	Steering wheel assembly – gray	8708949001	1	82.47	82.47
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280183	4	1	13898219-00	EM2EU-3402010E- V1H	Steering wheel assembly – gray	8708949001	1	82.47	82.47
	3003600	CHINA	BYDEUIL0001W2507026_06	SPS202507280184	5	1	13898219-00	EM2EU-3402010E- Y1H	Steering wheel assembly – gray	8708949001	1	82.47	82.47
	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290210	1	1	17399652-00	\	SC2EAU-2142700_repair kit for power domain control unit	9032899080	1	1063.16	1063.16
	3003649	CHINA	BYDEUIL0001W2507021_21	SPS202507290211	2	1	17399652-00	\	SC2EAU-2142700_repair kit for power domain control unit	9032899080	1	1063.16	1063.16

SC2EM-6205200

13451184-00

Rear left door lock body

assembly

8301209000

3

Y EUR FIVE THOUSAND TWO HUNDRED AND EIGHTY-SEVEN AND CENTS EIGHTY-FOUR (EUR 5287.84) ONLY.													
											88		5,287.84
290	903642	CHINA	BYDEUIL0001W2507009_49	SW1202507292386	1	1	17122501-00	SA3HKU-6801120	Driver's power seat sliding rail assembly	9401999000	1	90.07	90.07
300	003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292906	5	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
300	003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292905	4	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
300	003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292904	3	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
300	003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292903	2	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
300	003600	CHINA	BYDEUIL0001W2507026_10	SW1202507292902	1	1	13437984-00	SC2E-2904020A	Front right lower control arm assembly	8708801000	1	38.23	38.23
300	003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291447	2	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator upper	8708299000	1	11.6	11.6
300	003650	CHINA	BYDEUIL0001W2507024_15	SW1202507291446	1	1	13443024-00	SC2EM-5301570	Left connecting plate assembly of radiator upper	8708299000	1	11.6	11.6
300	003600	CHINA	BYDEUIL0001W2507026_05	SP2202507281603	1	1	13222666-00	SC2E-5305040	Gearshift control mechanism cover assembly	8708299000	5	25.92	129.6
300	003600	CHINA	BYDEUIL0001W2507026_04	SP2202507281602	1	1	13132985-00	EM2E-8107010	EM2E-8107010_Evaporator core assembly M00666	8415909000	1	39.85	39.85