Weather monitor product design specifications

• ESP32 feather microcontroller, or ATmega328P

• Input sensors: DHT11 Temperature and humidity sensor module

• Output: KY-012 active buzzer

• Output: 1 Motor Driver Board (e.g., Adafruit 2927)

• Output: 1 Stepper Motor (e.g., Amazon B00PNEQKC0)

Power: USBArduino IDE