

In normal circumstances Local Authority Building Control is required for new or replacement conservatory roofs and it is the installers responsibility to check whether Building Control is required. Although the Warmer Roof has Assent AND JHAI Building Control accreditation, this does not mean that Building Control is not required but having this accreditation, through Assent or JHAI, simplifies the Building Control application. It is likely that site inspection (s) will be carried out during the installation procedure of a replacement or new conservatory roof. Warmer Roof holds no responsibility if this advice is not followed. The Warmer Roof is only tested and certified by Assent Building Control Ltd and JHAI Building Control Ltd. Warmer Roof will not take responsibility for any Building Control other than Assent or JHAI. Please contact a member of staff if any further guidance is required.