



LIFTING EQUIPMENT INSPECTION REPORT	Area :	Inspection Date:	Inspection Time:	Previous sticker	Issued by
	Jubail	16/Aug/2025	08:00	27605	Zamil
Department/Contractor	Equipment No	Equipment Location:	Inspection Result :	New sticker No.	
METSCCO heavy steel industries Co Ltd.	EC180109	AMIRAL PROJECT / ARAMCO	Pass	ZAM-BS-28163	
Manufacturer:	Model:	Capacity:	Type:	Equipment serial Number	Sticker Expiration Date:
XCMG	XCT80	80 t	MOBILE CRANE TM-H	A010695	15/Nov/2025

Above equipment was inspected by **ZAMIL INSPECTION** accordance with applicable Saudi Aramco GI's, ASME and API standards.

Deficiencies that require corrective action listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	PERIODIC INSPECTION VISUAL AND FUNCTIONAL TEST WERE CARRIED OUT BASED ON ARAMCO GI 7.030, ASME B 30.5 & ASME B 30.10.	
2	THE EQUIPMENT CONDITION FOUND SATISFACTORY AT THE TIME OF INSPECTION.	
3	MAIN & AUX HOOK BLOCKS AND BOTH WIRE ROPES CONDITION FOUND SATISFACTORY.	
4	MAIN HOOK BLOCK SWL : 40 t / SN- EJ000035 / 4 PART LINES.	
5	AUX HOOK BLOCK SWL : 7 t / SN- EH000036 FLY JIB STOWED IN POSITION	
6	WIRE ROPE DIA : 20 MM / MVPI EXPIRY DATE - 3-05-2026 / PLATE NO : 7184 JAA.	
7	FOLLOW THE PROPER PM AS PER THE MANUFACTURE INSTRUCTIONS.	
8.	LOAD TEST WITNESS AT 100% OF RATED CAPACITY AS PER LOAD RATING CHART.	
9.	DRIVE CABIN DOOR LOCKS SHOULD BE MAINTAINED.	

RECEIVER NAME	BADGE No	TELEPHONE No	INSPECTOR NAME	CERTIFICATE NO	TELEPHONE No
SURESH	CRC011520	0535994769	Nabeel Ahmad	SAP No 80019127	0540741701
					
RECEIVER SIGNATURE			INSPECTOR SIGNATURE		

When re-inspection is requested, a complete copy of this report should be ready reviewed by the inspector.

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES			
PROJECT TITLE ARAMCO	WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.: ZAMIL-R129530
EC180109	MOBILE CRANE TM-H		A010695	
CAPACITY (SWL)	MANUFACTURER		FACILITY / LOCATION	
80 t	XCMG		Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE	RFI No.	TASK COMPLETED DATE	EQUIPMENT OWNER	
14/Aug/2025		16/Aug/2025	METSCCO heavy steel industries Co Ltd.	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
1	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	☒	☐	☐	
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	☒	☐	☐	
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	☒	☐	☐	
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	☒	☐	☐	
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	☒	☐	☐	
1.6	Work areas chart is available	G.I. 7.025 ASME B30.5 Sec 5-1.1.3(2)	☒	☐	☐	
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	☒	☐	☐	
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	☒	☐	☐	
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4	☒	☐	☐	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4	☐	☐	☒	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	☒	☐	☐	
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	☒	☐	☐	
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	☒	☐	☐	
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	☒	☐	☐	
2	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	☒	☐	☐	
2.2	Two (2) Two (2) full wraps of rope remain on the drum when hook is in the extreme low positionfull wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	☒	☐	☐	
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES			
PROJECT TITLE ARAMCO	WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.: ZAMIL-R129530
EC180109	MOBILE CRANE TM-H		A010695	
CAPACITY (SWL)	MANUFACTURER		FACILITY / LOCATION	
80 t	XCMG		Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE	RFI No.	TASK COMPLETED DATE	EQUIPMENT OWNER	
14/Aug/2025		16/Aug/2025	METSCCO heavy steel industries Co Ltd.	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	☒	☐	☐	
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	☒	☐	☐	
2.6	Auxiliary travel controls function correctly for multiple control-station cranes	ASME B30.5 Sec: 5-1.5.1	☒	☐	☐	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☒	☐	☐	
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	☒	☐	☐	
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2	☐	☐	☒	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	☒	☐	☐	
2.14	All cab glazing are safety glazing material	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	☒	☐	☐	
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	☒	☐	☐	
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7	☐	☐	☒	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec:5-1.9.1	☐	☐	☒	
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec:5-1.9.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES			
PROJECT TITLE ARAMCO	WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.: ZAMIL-R129530
EC180109	MOBILE CRANE TM-H		A010695	
CAPACITY (SWL)	MANUFACTURER		FACILITY / LOCATION	
80 t	XCMG		Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE	RFI No.	TASK COMPLETED DATE	EQUIPMENT OWNER	
14/Aug/2025		16/Aug/2025	METSCCO heavy steel industries Co Ltd.	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.23	Boom shut-off or hydraulic reliefs provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	☒	☐	☐	
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	☒	☐	☐	
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	☒	☐	☐	
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 sec: ASME B30.5 Sec:5-2.1.3 (d)	☒	☐	☐	
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	☒	☐	☐	
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	☒	☐	☐	
2.34	All tires are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	☒	☐	☐	
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	☒	☐	☐	
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES			
PROJECT TITLE ARAMCO	WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER EC180109	EQUIPMENT DESCRIPTION/TYPE MOBILE CRANE TM-H	SERIAL NO. A010695	REPORT No.: ZAMIL-R129530
CAPACITY (SWL) 80 t	MANUFACTURER XCMG	FACILITY / LOCATION Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE 14/Aug/2025	RFI No.	TASK COMPLETED DATE 16/Aug/2025	EQUIPMENT OWNER METSCCO heavy steel industries Co Ltd.

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	☒	☐	☐	
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.52	Rope is free of kinking, crushing, birdcaging, or any other damage resulting in distortion of the rope structure • No more 1 broken wire protruding from the core • There are no reductions from nominal rope diameter of more than 5% For running ropes: • No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay For rotation resistance ropes : • No more than 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters • Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	☒	☐	☐	
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE ARAMCO		WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER	EQUIPMENT DESCRIPTION/TYPE		SERIAL NO.	REPORT No.: ZAMIL-R129530
EC180109	MOBILE CRANE TM-H		A010695	
CAPACITY (SWL)	MANUFACTURER		FACILITY / LOCATION	
80 t	XCMG		Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE	RFI No.	TASK COMPLETED DATE	EQUIPMENT OWNER	
14/Aug/2025		16/Aug/2025	METSCCO heavy steel industries Co Ltd.	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.59	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	☒	☐	☐	
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	☒	☐	☐	
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5	☒	☐	☐	
3.2	Crane level indicator is fitted and working	ASME B30.5	☒	☐	☐	
3.3	Engine gauges and associated indicators are working	ASME B30.5	☒	☐	☐	
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5	☒	☐	☐	
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5	☒	☐	☐	
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.5	☒	☐	☐	
3.7	Hook assemblies are equipped with safety latches	G.I. 7.030	☒	☐	☐	
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.5	☒	☐	☐	
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.5	☒	☐	☐	
3.10	Safe working load of hook is clearly marked on the item	ASME B30.5	☒	☐	☐	
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10	☒	☐	☐	
3.12	Hook is not bent or twisted • Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations	ASME B30.10	☒	☐	☐	
3.13	Hook is not distorted in the throat opening • Max. allowable throat opening is 5% not to exceed 1/4 in. (6 mm) compared to new hook, or as per manufacturer recommendations	ASME B30.10	☒	☐	☐	
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10	☒	☐	☐	
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES			
PROJECT TITLE ARAMCO	WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER EC180109	EQUIPMENT DESCRIPTION/TYPE MOBILE CRANE TM-H	SERIAL NO. A010695	REPORT No.: ZAMIL-R129530
CAPACITY (SWL) 80 t	MANUFACTURER XCMG	FACILITY / LOCATION Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE 14/Aug/2025	RFI No.	TASK COMPLETED DATE 16/Aug/2025	EQUIPMENT OWNER METSCCO heavy steel industries Co Ltd.

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10	☐	☐	☒	
3.17	Inoperative latch (if provided) — any damaged latch or malfunctioning latch that does not close the hook's throat	ASME B30.10	☒	☐	☐	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.10	☒	☐	☐	
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.10	☒	☐	☐	
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.10	☒	☐	☐	
3.21	Reverse travel alarm is operational	ASME B30.5	☒	☐	☐	
3.22	Turning signals and indicators are working correctly	ASME B30.5	☒	☐	☐	
3.23	Road lighting, including spotlights, are in good condition and operable	ASME B30.5	☒	☐	☐	
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5	☒	☐	☐	
4.0	CRAWLER CRANE					
4.1	Track pads are undamaged and drive chain are tensioned	ASME B30.5	☐	☐	☒	
4.2	Drive sockets and drive chain tumblers are serviceable	ASME B30.5	☐	☐	☒	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5	☐	☐	☒	
4.4	Track idlers are serviceable	ASME B30.5	☐	☐	☒	
4.5	Back boom stops are functioning	ASME B30.5	☐	☐	☒	
4.6	Back A-Frame is in good condition	ASME B30.5	☐	☐	☒	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5	☐	☐	☒	
4.8	Power low lowering is operational	ASME B30.5	☐	☐	☒	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5	☐	☐	☒	
4.10	Boom chords and lacing are undamaged (bent)	ASME B30.5	☐	☐	☒	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5	☐	☐	☒	
4.12	Pendant ropers are showing no broken wires (see no. 48)	ASME B30.5	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE ARAMCO		WBS/BI/JO NUMBER ZAM-14031-08-25	INSPECTION COMPANY ZAMIL Inspection & Cont.	

EQUIPMENT ID NUMBER EC180109	EQUIPMENT DESCRIPTION/TYPE MOBILE CRANE TM-H		SERIAL NO. A010695	REPORT No.: ZAMIL-R129530
CAPACITY (SWL) 80 t	MANUFACTURER XCMG		FACILITY / LOCATION Jubail.AMIRAL PROJECT/ARAMCO	
REQUESTED INSPECTION DATE 14/Aug/2025	RFI No.	TASK COMPLETED DATE 16/Aug/2025	EQUIPMENT OWNER METSCCO heavy steel industries Co Ltd.	

ITEM No.	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
4.13	Operation of steering brakes is satisfactory	ASME B30.5	☐	☐	☒	
4.14	Main machinery guarding is in place	ASME B30.5	☐	☐	☒	
4.15	Main clutch is fully operational	ASME B30.5	☐	☐	☒	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5	☐	☐	☒	

REMARKS:

REFERENCE DOCUMENTS:
1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes 2- ASME B30.10 - 2019 Issue: Hooks 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification

Load Tested By (If Applicable): Name, Signature, & Date: ☒ Inspected ☐ Witnessed by 3rd Party Certified Inspector: Name, Signature, Certificate No. & Company: Nabeel Ahmad , SAP No 80019127 , ZAMIL Inspection & Cont.	
User Representative: Name, Signature, & Date: SURESH , 16/Aug/2025	



Zamil Inspection & Contracting Co.



+966555052687



info@zamil.sa

NO. : **ZAM-BS-28163**

EQUIP. No : EC180109

EQUIP. S.N: .A010695

DATE INSPECTED: .16/Aug/2025

NEXT INSPECTION DATE: 15/Nov/2025

INSPECTED BY: Nabeel Ahmad

Inspector / SAP NO. : SAP No 80019127

SA Inspection dept. Approval Contractor Agency