



RAPPORT D'INTERVENTION

INFORMATIONS DU CLIENT & SITE

Client : DGS Africa | Contact : +221 77 123 45 67
Site : Dakar, Plateau, Rue 123

DÉTAILS DE L'INTERVENTION

Date/Heure : 24/06/2026 08:02:00 au 27/06/2026 08:02:00
Technicien(s) : Moussa Diop
Type : Climatisation | Équipement : frigo

TRAVAUX RÉALISÉS

rufvnd

Diagnostic :
rnivnnjhxd

NOTES DU TECHNICIEN

[SIMULATION] L'équipement était totalement hors service. J'ai dû réinitialiser la carte mère principale et vérifier l'alimentation. Tout semble stable maintenant.

PHOTOS D'INTERVENTION

[AVANT] -

```
C:\sensante> venv\Scripts\activate

(venv) C:\sensante>pip install fastapi uvicorn
Collecting fastapi
  Downloading fastapi-0.136.1-py3-none-any.whl.metadata (28 kB)
Collecting uvicorn
  Downloading uvicorn-0.46.0-py3-none-any.whl.metadata (6.7 kB)
Collecting starlette>=0.46.0 (from fastapi)
  Downloading starlette-1.0.0-py3-none-any.whl.metadata (6.3 kB)
Collecting pydantic>=2.9.0 (from fastapi)
  Downloading pydantic-2.13.4-py3-none-any.whl.metadata (109 kB)
Collecting typing-extensions>=4.8.0 (from fastapi)
```

[APRES] -

```
(venv) C:\sensante>pip freeze > requirements.txt  
  
(venv) C:\sensante>
```

RECOMMANDATIONS & REMARQUES

Recommandations :

rytyfhff

SIGNATURE DU CLIENT

A rectangular box containing a handwritten signature in black ink. The signature is stylized, with a large, sweeping 'S' shape and a horizontal line crossing it.

Signé électroniquement le : 24/06/2026 08:08:02

DYNAMIC GLOBAL SERVICES (DGS Africa)

Dakar, Sénégal | +221 33 800 00 00 | contact@dgs-africa.com