Corrective & Preventive Action

AutoSaarthi | generated 08 Sep 2026 04:42

CAPA ID	CAPA-2026-014
Component	water_pump
Defect mode	Seal wear - coolant loss > 5% & rising
Batch	BATCH-2024-Q3-NSK
Plant	Nashik
Status	draft
Affected vehicles	5

Root cause

Supplier's compound changed; cost impact Rs 18,500 per breakdown vs Rs 2,400 to repair. Engineer noted "heat soak" as the driver...

Corrective action

Recall batch <BATCH-2024-Q3-NSK> for seal replacement.

Generated by the AutoSaarthi agent platform. Figures are produced by the models and rules described in the system documentation; this document is a record of what the system computed, not an engineering sign-off.