StratX™ Lung Report



Patient ID 565

Upload Date

Aug. 22, 2024

Scan ID 2

283987 Report Date


Sep. 03, 2024

CT Scan Date Aug. 13, 2024

Scan Comments

Possible prior implant in airways

SUMMARY



Results not available due to Prior implant.

KEY

≥ L

≥ 70% Voxel Density Less Than -910 HU



≥ 60 – < 70% Voxel Density Less Than -910 HU



≥ 50 – < 60% Voxel Density Less Than -910 HU



< 50% Voxel Density



Less Than -910 HU



≥ 95% Fissure Completeness



≥ 80 – < 95% Fissure Completeness

< 80% Fissure Completeness

RESULTS

		_17	г 1		I IN I	
RI	u	п.		_u	צוו	U

F	RUL	RUL+R	RML	RML	RLL
	67	86		75	86
_					

%	Voxel [Density
Less ⁻	Γhan -9	10 HÚ

% Fissure Completeness

52

68

50

46

% Voxel Density Less Than -950 HU

6 52

25

28

1266

Inspiratory Volume (ml)

2065 2413

348

LEFT LUNG

Results not available due to Prior implant.

StratX® Post-treatment Report



Assessment Details

StratX Patient ID: StratX Scan ID: CT Scan Date: Comments:

LUL	
565	
283987	_
13-Aug-2024	_
NA	
-	_

Lobar Volume Reduction

Baseline Volume (mL): Follow-up Volume (mL):

TLVR (mL): TLVR %

N/A
1522
N/A
N/A%

	Intermediate Level			Segmental Level			Subsegmental Level		
	Airway	Placed	Valve Status	Airway	Placed	Valve Status	Airway	Placed	Valve Status
			No valve observed	LB1+2	No	No valve observed	LB1+2a	Yes-1	Valve present
	Superior Division						LB1+2b	No	No valve observed
1	LUL Bronchus (LB1+2 & LB3)						LB1+2c	Yes-1	Valve present
LUL				LB3	No N	No valve observed	LB3a	No	No valve observed
							LB3b	Yes-1	Valve present
		ingular chus (LB4 & No observed		LB4	No	No valve observed	LB4a	No	No valve observed
	Line, de la						LB4b	No	No valve observed
Bronchu	Bronchus (LB4 &			LB5	Yes-1	Valve present	LB5a	No	Proximal valve present
	[53]						LB5b	No	Proximal valve present

Position Analysis

Quantity of Valves Observed:

4


Study Summary:

An airway identified with no valve in place or signs consistent with a leak surrounding a valve.

StratX® Post-treatment Report



Valve Images



Lobar Volumes

Lobe	Baseline Volume (mL)	Follow-up Volume (mL)	Volume Change (mL)	Volume Change %
LUL	N/A	1522	N/A	N/A
LLL	N/A	1515	N/A	N/A
RUL	N/A	2065	N/A	N/A
RML	N/A	348	N/A	N/A
RLL	N/A	1266	N/A	N/A
TOTAL	N/A	6716	N/A	N/A

If there is a device malfunction, please contact your Pulmonx representative to report a complaint.

StratX[®] Post-treatment Report



General Disclaimer: The valve status data shared in this report is based on the review of CT imagery by a radiologist. The data may not match observations made with direct optical visualization during bronchoscopy.

Valve Status Terminology:

"Valve Present" — Valve is present in this airway.

"Valve present with visible leak" — Valve is present in this airway with visible leak surrounding the valve.

"No valve observed" — A valve was not observed in this airway or proximal to this airway.

"Valve present with atypical appearance" — Valve is present in this airway with atypical observation distal to the valve.

"Proximal valve present" — Valve is present in proximal airway.

"Airway not present" — The airway is not included in the patient's anatomy.

"Other valve present" — A non-Zephyr valve or other implant is present in this airway. The radiologist cannot comment on valve seal or possible leak.

"Proximal valve leak" — Valve is present in proximal airway and with visible leak surrounding the valve.