



3 2 ZONE REV DESCRIPTION DATE APPROVED **Build Opions** Necessary AT90-TQFP Cannot build 1.2 in conjunction Includes Build option 1 1.2 AT90-QFN Cannot Build 1.1 in conjunction Includes Build option 1 1.3 USB via CN2 Cannot Build 1.4 in conjunction Includes Build option 1 USB via JP5 Cannot build 1.3 in conjunction Includes Build option 1 1.4 Optional 12V ports Micro SD card Option Who Fix Date comments Issue Date Who Review Sense R's Need to Be larger than 0603 4/3/2014 Matt 4/4/2014 Switched to 0805 for all controllers Tom UPDATED POWER BLOCK See notes GND ISSUES AGND AND GND HAVE SAME NAME Seperated GNDs Added Fuse and Dcap to input see RED Elecrolitic caps missing Values Matched all to 100uF add PN for electrolitic caps 36VTol Need to review fet function Sim shows High loss No current limit on Stop Headers Added 220 current limiter Pattern F1 4/10 Matt 4/10 Added New Pattern Library 'fuses' Tom Pattern U\$8 4/10 Added new pattern to crystal library is now X1 Matt 4/10 Pattern S1 to be removed as AT90 will do this 4/10 Matt 4/10 Updated to rush 2pin .100" and is now JP5 Pattern JP14 4/10 Matt 4/10 LED Buton Header and Debounce 4/12 Motor dirver headers 4/13 LED's for ATTiny 4/12 Both are green now and 603 Silk on pin headers 4/13 JP1 Left as a non locking 5 pin header L1 & L2 Pattern 4/13 Add test points for var signals U7 Pattern 4/13 Q6,7,8 Import error from Eagle S and D swap 11/06/14 Designed by RUSHdesign for Solidoodle Change log REV DA SIZE FSCM NO. DWG NO. SD5AA SCALE Sheet 3 4 3 2