

RESIDENTIAL PROPERTY INSPECTION REPORT

Tucson House
2847 E Speedway Blvd, Tucson, AZ

PLUMBING SYSTEM

Plumbing in excellent condition. No signs of corrosion or leaking at visible connections.



Photo: PLUMBING SYSTEM

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.