

RESIDENTIAL PROPERTY INSPECTION REPORT

Seattle Townhouse

742 Pine St, Seattle, WA

FOUNDATION & STRUCTURAL

Foundation walls appear structurally sound with no visible signs of settlement or movement. No remediation recommended.



Photo: FOUNDATION & STRUCTURAL

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.