

RESIDENTIAL PROPERTY INSPECTION REPORT

Boston New Construction

789 Commonwealth Ave, Boston, MA

BASEMENT & MOISTURE

Basement walls are completely dry with no signs of moisture or water intrusion. Concrete is in excellent condition with proper sealant applied.




Photo: BASEMENT & MOISTURE

SUMMARY

Property exceeds expectations. All systems in excellent working order. Highly recommended.