


Nonuniform xy pressure solve passes; its straight material path fails
Two columns · full symmetric strain · no accepted advancing state

Solved pressure on the force mesh



Rejected material path endpoint

