

Synthetic Well Completion Report — OIL-102

NOTICE

SYNTHETIC TRAINING DOCUMENT — NOT REAL OIL DATA.

Well Information

Field	Well ID	Latitude	Longitude	Spud	Completion
North Ridge	OIL-102	26.1234	94.1234	2024-02-03	2024-03-28

Formation Tops

Formation	Top MD	Bottom MD	Lithology
F-A	0	1450	Shale
F-B	1450	2280	Sandstone
F-X	2280	3190	Fractured limestone
F-Y	3190	3650	Shale/sandstone

Major Events

Depth	Event	Severity	Cause	Mitigation
2845 m	Mud loss	HIGH	Fractured limestone	LCM treatment
2910 m	Torque spike	MEDIUM	Formation interaction	Reduced WOB/RPM
3120 m	Stuck pipe	HIGH	Differential sticking	Circulation + freeing procedure

Lessons Learned

Fractured limestone around 2800–2950 m was associated with severe losses.

Torque increased near 2910 m.

Stuck pipe at 3120 m was attributed to differential sticking.