

Project Details

Project Name:	Waitrose Newport	Start Date:	23 Aug 2026
Project Ref:	I0000195	End Date:	27 Nov 2026
Version Number:	N/A	Created By:	Daniel Boden
Project Description:	L4L scheme		

Contact Details

Name:	Daniel Boden
Number:	07918 777 634
Email:	daniel.boden@ich-projects.co.uk
Project Address:	Waitrose Audley Road Newport Shropshire TF10 7DS

Nearest Hospital

Name:	The Princess Royal Hospital
Address:	Apley Castle Telford Telford and Wrekin England United Kingdom TF1 6TF

Attending Non-Employees

Gary Bathurst

Site Manager Details

Contact Name:	Gary Bathurst
Contact Number:	07813 792 311
Contact Email:	

Site Supervisor Details

Contact Name:	
Contact Number:	
Contact Email:	

Site Details

Site Working Hours:	06:00 - 18:00
Site:	ICH - Projects
Department:	N/A

Legislation

- Health and Safety Work Act 1974
- The Management of Health and Safety at Work Regulations 1999
- Workplace (Health Safety and Welfare) Regulations 1992
- The Control of Asbestos Regulations 2012
- Provision and Use of Work Equipment Regulations (PUWER) 1998
- The Reportable Injuries Diseases & Dangerous Occurrence Regulations 2013 (RIDDOR)
- Control of Substances Hazardous to Health Regulations 2002
- The Work at Height Regulations 2005 (amended 2007)
- The Personal Protective Equipment at Work Regulations 1992
- The Manual Handling Operations Regulations 1992
- Electricity at work regulations 1989
- Environmental Protection Act 1990
- Waste (England and Wales) Regulations 2011
- Controlled Waste (England and Wales) Regulations 2012
- The Confined Spaces Regulations 1997
- The Health and Safety at Work etc. Act 1974 (General Duties of Self-Employed Persons) (Prescribed Undertakings) Regulations 2015
- The Construction (Design and Management) Regulations 2015
- Lifting Operations and Lifting Equipment Regulations 1998

Sequence of Works

Critical Stages: (must be undertaken in correct sequence).

Critical Stages

- o On arrival site contact made and site induction undertaken if required
- o Access and check the site logbook and asbestos register, collect the equipment's manufacturer's specifications (if available) and complete the site permit to work if required.
- o Ensure the work area is safe, free from obstructions and egress and suitable lighting is available.
- o Ensure site specific risk assessment is completed on PDA.
- o Wear appropriate PPE for task.
- o If working outside, please ensure appropriate clothing and weather protection is used.
- o If working at height please follow appropriate RAM's/Policy.
- o Strip out existing equipment as required and remove from work area.
- o Install as per manufacturer's instructions.
- o Commission equipment and carry out safety checks as per manufacturer's instructions.
- o Place equipment back online and into service.
- o Clear away all tools and unused materials. Leave in a safe condition.
- o Report back to site contact, sign off work permit and any other relevant documentations.

Approved Codes & Practice

- First aid at work: the Health and Safety (First-Aid) Regulations 1981 L74 (Third Edition) Published 2013
- Reporting accidents and incidents at work A brief guide to the Reporting of Injuries Diseases and Dangerous Occurrences Regulations 2013 (RIDDOR) INDG453(rev1) Oct 2013
- Managing health and safety in construction Construction (Design and Management) Regulations 2015. Guidance on Regulations L153 2015
- Personal protective equipment at work regulations 1992 Guidance on Regulations L25 (3rd Ed.) 2015
- Safe use of lifting equipment. Lifting Operations and Lifting Equipment Regulations 1998 L113 (2nd Ed.) 2014
- Safe use of work equipment. Provision and Use of Work Equipment Regulations 1998. L22 2014 (4th Ed) ACOP and Guidance
- Whole body vibration. The Control of Vibration at Work Regulations 2005. Guidance on Regulations L141 2005
- Construction (Head Protection) Regulations 1989 L102 (2nd Ed.) Guidance on Regulations. 1998
- Control of substances hazardous to health (5th edition) : the Control of Substances Hazardous to Health Regulations 2002 (as Amended) L5 ACOP and Guidance 2013 (6th Edition)

Tools & Equipment

Air Conditioning Installation

- LOTO hasp, padlock & keys
- Handheld refrigerant leak detector
- Hand Tools
- Digital Thermometer

Gas Works

- Gas analyser equipment
- Calibrated electrical test equipment
- Hammer Drill Cordless
- Isolation Tags/Locks

Plumbing

- Wrench

Hazards



Flammable



Hot Surface



Electrocution
Risk



Slippery
Floor



Slips and
Trips



Cutting
Risk



Gas Bottle



Falling
Objects



Electric
Shock



Battery
Charging



Gas under
pressure

Emergency Procedures & First Aid

- First Aid and safety notice board must be present and visible with relevant information at all times. It is the responsibility of the client or main contractor to make available the correct number of fully stocked First Aid boxes and ensure the nominated person takes full

responsibility of first aid requirements and planning

- All site emergency procedures must be adhered to and it is the responsibility of the client or main contractor to ensure these are followed at all times. At point of induction all relevant or amended details and information are to be issued to persons working in or around the area.
- At least one appointed person
- Follow site emergency procedures.

Welfare Requirements

- Toilets
- Drinking water
- Rest Facilities

PPE Requirements



Safety
Glasses



Hardhat



Hearing
Protection



Wear Foot
Protection



Wear Hand
Protection



Hi-Vis



Mask



Wear Eye
Protection



Site Specific
Requirements

Secure Working Areas

- Various Only contractors to be present during activity

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessments

Risk Assessment Name:

Pipework modifications / install new pipework

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Daniel Boden

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

Pipework modifications / install new pipework

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Confined spaces Consequence Asphyxiation through lack of oxygen, lack of emergency response resulting in worsened injuries, falls from height etc.	16	a) Suitable emergency procedures are arranged with the client when working in confined spaces. b) Suitable access / egress is maintained at all times. c) Sufficient lighting should be in place at all times. d) CO2 extinguishers are not used when working in a confined space	4	2	8			

COSHH Consequence Exposure to harmful substance causing acute and chronic ill health	16	Employees are required to follow the documented ICH COSHH risk assessment and Safety Data Sheet when working with hazardous chemicals. Appropriate PPE is provided and worn in the form of gloves, safety glasses and hard hats. Specific PPE is worn by the employee. First aid kit are stored in the Office.	4	1	4		
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking. Lone workers to regularly be in contact with management team and follow ICH Lone Worker Policy.	4	2	8		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers. Any manual handling training includes the need to avoid twisting, stooping or reaching to lift or deposit the load. Arrangements are made for the issue of protective clothing and equipment i.e. gloves, safety footwear etc. Storage arrangements will be made to ensure that the heaviest loads are in the most convenient position i.e from knee to shoulder range.	4	2	8		
Physical injury / risk of disease	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls	4	2	8		

Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances without using the correct protection, creams etc.		c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis. c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.					
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.	2	2	4		
Working at height Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	a) Engineers are trained in the safe use of ladders and stepladders. b) IPAF training for using a MEWP is provided to all engineers. c) Working area is cordoned off when working at height when deemed necessary by their risk assessment. d) Engineers are required to follow the documented ICH policy for working at height. e) Engineers to wear bump caps and safety glasses when working at height above suspended ceilings. f) PASMA training for using Podiums and scaffold	3	2	6		

		h) Emergency rescue plan complete and accessible for appointed emergency contact.					
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Hand Tools Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	3	1	3		
Moving and handling delivery of materials or equipment Consequence Heavy items causing musculoskeletal injuries causing long term injury.	9	The delivery driver is to avoid manual handling beyond their capability, which they believe may cause injury. The delivery driver is to ensure mechanical lifting aids (telehandler, pallet truck etc.) are used to offload materials wherever possible. The delivery driver is to ensure the correct loading of delivery vehicles prior to the vehicles leaving the materials yard and is to ensure the security of the load for transportation. Materials are to be palletted and wrapped wherever possible. The delivery driver is to ensure that delivery vehicles are loaded in the correct order of the deliveries so as to eliminate the need for re-stacking	3	1	3		

		materials after the first delivery has been made. No one is to enter the back of the vehicle unless suitable edge protection is in place to prevent a fall from height. Where suitable edge protection is unavailable, a restraint lanyard will be used to restrict access to any leading edges.					
Work in Occupied Premises Consequence Injury to occupants from tools, machinery, falling objects, or vehicle movements Claims, complaints, or reputational damage Work stoppages due to unsafe proximity	12	Due consideration is given to the requirements of the Construction (Design and Management) Regulations 2015 which may apply. Information obtained from the owner or occupier of the premises regarding potential hazards or arrangements relating to health and safety. The work is carefully assessed and planned to identify the health and safety precautions necessary to protect the occupiers from Company activities. Care is taken to ensure that housekeeping is maintained to a high standard, not least in relation to means of escape routes, removal of debris and spillage from floors, waste disposal, tools, equipment, and trailing leads etc. Areas where work is taking place are not left unattended unless tools and equipment have been removed and the area made safe, either by prevention of access or other means	4	1	4		
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10		

Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3		
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Working at Height

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

General working at height

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
General hazards Consequence Electrocution Lighting Noise Adverse weather	16	a) Suitable training provided to all worker covering general risks relevant to the business. b) Portable electrical appliances are periodically tested. c) Engineers use are required to use an approved and calibrated tester to check for voltage. d) All live testing must follow the documented Electrical Isolation & Live Working Policy. e) Engineers are instructed to report any lighting levels issues to the customer. Two engineers are deployed where the problem persists.	4	2	8			

		f) Provision of a temporary lighting solution where required (torches/lamps available) or issue raised with site management prior to commencement of work. g) Sun block to be worn where required including head protection. h) No work is undertaken during adverse weather conditions, e.g. storms, icy or snowy conditions or strong winds.					
Emissions from stacks, extraction ducts or electrical systems Consequence Exposure to harmful substance causing acute and chronic ill health	12	a) Checks made prior to site visit to establish if such things are in the vicinity of the work area. b) Such work is avoided if necessary and a dynamic risk assessment would be undertaken.	4	1	4		
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8		
Physical injury / risk of disease Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.	4	2	8		

without using the correct protection, creams etc.		c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.					
Podium and Mobile Towers Consequence - Falling through the barrier or gate - Overturning of equipment - Tools etc. falling onto person(s) below. - Slipping from ladder rungs or steps - Collapse of equipment	12	a) Checks are undertaken to ensure that the gate or barrier is always closed prior to commencement of work when deemed necessary by their risk assessment. b) Checks carried out to ensure wheels or feet are in contact with a firm surface. c) Equipment is not used on uneven, slippery, sloping or soft ground. d) Outriggers are used where required. e) Castors are locked in position. f) Where required exclusion zones are established around / under the work area. g) Where required lanyards / toolbelts used to retain equipment when working at height. h) The equipment is not moved whilst operators are on the tower. i) Manufacturer's instructions always adhered to. j) Work is accessible without overreaching. k) Equipment is only erected, dismantled and altered in accordance with manufacturer's guidance.	3	2	6		
Step Ladders / Ladders / Telescopic & Combination Ladders / Mobile Steps Consequence ☐ Falling from the step ladder / ladder / mobile steps e.g. over- reaching, slipping, equipment not placed on level ground, ladder not properly secured, ladder etc. being struck by a moving vehicle. ☐ Failure of the step ladder / ladder / mobile steps e.g. due to inadequate maintenance, overloading etc. ☐ Tools etc. falling onto person(s) below.	12	a) Staff have been provided with sufficient information, instruction and training. Documented records are available. b) Ladders (if used) are only used for low-risk, short duration work. c) Domestic step ladders / ladders are not used. Only industrial / tradesmen type step ladders / ladders are used. d) Regular inspections undertaken of the step ladders / ladders / mobile steps etc. Documented records are available.	4	2	8		

		e) Users ensure step ladder / ladders are not overloaded. f) Where required exclusion zones are established around / under the work area. g) Where required lanyards / toolbelts used to retain equipment when working at height.					
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Emergency Procedures - General Consequence Engineer unable to escape site in an emergency situation	12	Operative to be informed of client's emergency arrangements at induction prior to start of work At least one operative to be first aid trained and First aid boxes are available in work vehicles In the event of an Emergency Situation the site should be evacuated immediately, and all personnel removed to the muster point as soon as all persons are at a safe location the emergency services should be contacted.	4	2	8		
Falling objects from work area above Consequence Injury to persons below from falling objects	12	Wear Safety Hard Hat Wear Safety Boots Close down Working area above and inspect prior to work date	4	2	8		
Stepladders & Hop Ups Consequence Falling from unsafe use of stepladders	12	Pre user checks to look for any obvious visual defects including stiles, feet, rungs, locking mechanisms etc. Ensure all four stepladder feet are in contact with the ground and the steps	4	2	8		

and Hop ups, leading to broken or injured limbs		are level. Only light materials and tools to be carried. No overreaching when working from a stepladder Standing and working on the top three steps is not advised unless there is a suitable handhold available. Ensure any locking devices are fully engaged. Stepladder to be positioned & face the work activity and not side on. Three points of contact at the work position to be maintained Operatives to try and avoid side-on loadings such as side-on drilling through solid materials Where side on loadings cannot be avoided, operatives will look to prevent steps from tipping over by either tying the steps or looking to use a more suitable type of access equipment.					
Working at Height - MEWP Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	The site is checked to ensure that the mobile elevating work platform can be used safely, in accordance with the manufacturer's recommendations. The maximum safe working load limits are established before the platform is put into use. Only trained and authorised persons operate and work from this equipment. Prior to use the equipment is checked, e.g. tyres, brakes, lights, fuel/power, leaks, general defects etc., in accordance with the manufacturers guidance. Arrangements are made to ensure that there are no obstructions, especially overhead cables etc, in areas where the platform is to be taken or used. Arrangements are made to clear working areas around the equipment by use of warning signs, barriers, cones etc. This is especially important if work takes place where public have access.. Arrangements are made to ensure the stability of equipment, if it is not possible	4	2	8		

		to make full use of outriggers etc. that may be fitted. Good visibility and lighting during work operations is essential. Electrical supply is routed safely and connected to the mains in an approved manner. Access to the platform is only made at ground level. The platform is fully guarded during. Work is done only from within the platform area, without having to lean out. Emergency stop and isolation switches etc, are clearly marked and operatives using the equipment are aware of the emergency procedures. Emergency rescue plan is complete and accessible for the appointed rescue person .					
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Warm clothes provided by ICH	4	1	4	Plenty of fluids available and take regular breaks	
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10		

Hand Tools Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	2	1	2			
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3			

Additional Control Actions

Owner

Completion Date

Initials

Dynamic risk assessment used to assess the weather conditions prior to works commencing.

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Using a MEWP

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

Using a MEWP to work at height

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
General Hazards Consequence - Contact with vehicles / pedestrians - Contact with electrical services - Crushing - Adverse weather conditions	16	a) All suitable records for certification and maintenance is checked prior to use when deemed necessary by their risk assessment. b) Safe working limit not exceeded when deemed necessary by their risk assessment. c) Work area is cordoned off prior to any work commencing when deemed necessary by their risk assessment. d) Work area checked for overhead electrical services and potential contact points for crushing prior to moving the MEWP. e) Hard hat worn where necessary.	4	2	8			

		f) Work is not undertaken in adverse weather conditions, such as heavy rain, strong winds etc.					
Operative thrown from carrier Consequence Falls resulting in serious injury or being trapped with harness attached to the MEWP	20	a) IPAF trained engineer uses MEWP. Operative wears work restraint. The MEWP is only moved if designed to be moved whilst carrying operative. b) Operative does not overreach.	5	1	5		
Overturning Consequence Serious injury resulting in broken bones, concussion, crushing etc.	20	a) IPAF trained engineer chooses, inspects and uses the MEWP. Checks carried out for manhole covers, soft ground, potholes etc. b) Engineers follow the IPAF training and adhere to these policies and procedures.	5	1	5		
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	12	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers. Any manual handling training includes the need to avoid twisting, stooping or reaching to lift or deposit the load. Arrangements are made for the issue of protective clothing and equipment i.e.	4	1	4		

		gloves, safety footwear etc. Storage arrangements will be made to ensure that the heaviest loads are in the most convenient position i.e from knee to shoulder range.					
Reversing, driving or pushing MEWPs Consequence Collisions with objects and persons causing damage or serious injury	15	Use mirrors Use reverse camera Don't drive at all!	5	1	5		
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	12	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.	4	1	4		
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Warm clothes provided by ICH	4	1	4	Plenty of fluids available and take regular breaks	
Bad or inappropriate lighting	6	Correct lighting is established prior to work by the dynamic risk assessment.	2	1	2		

Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.		Additional lighting to be ordered and used correctly if required.					
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10		
Hand Tools Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	2	1	2		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3		

Additional Control Actions

Owner

Completion Date

Initials

Dynamic risk assessment used to assess the weather conditions prior to works commencing.

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Purge Gas Supply Pipe Work up to 1m³

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

To purge gas supply pipe - work up to 1m³

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
COSHH Consequence Exposure to harmful substance causing acute and chronic ill heal	16	Employees are required to follow the documented ICH COSHH risk assessment and Safety Data Sheet when working with hazardous chemicals. Appropriate PPE is provided and worn in the form of gloves, safety glasses and hard hats. Specific PPE is worn by the employee. First aid kit are stored in the Office.	4	1	4			
Exposure to gas Consequence	20	a) Engineers are required to be Accredited Certification Scheme (ACS) trained.	5	2	10			

Nose and throat irritation, headaches, dizziness, nausea, vomiting, confusion and breathing difficulties							
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8		
Working at height Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	a) Engineers are trained in the safe use of ladders and stepladders. b) IPAF training for using a MEWP is provided to all engineers. c) Working area is cordoned off when working at height when deemed necessary by their risk assessment. d) Engineers are required to follow the documented ICH policy for working at height. e) Engineers to wear bump caps and safety glasses when working at height above suspended ceilings.	3	2	6		
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Electricity	20	Suitable training provided to all engineers covering general risks	5	2	10		

Consequence Electrocution Death		relevant to the business. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.					
Hand Tools Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	2	1	2		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100DbA less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Install Electric Water Heater

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

To install new electric water heater

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Asbestos Consequence Exposure to asbestos fibers causing asbestos related illness.	20	All operatives are given suitable training relating to asbestos awareness. If fibrous materials are encountered, work is stopped, and the area is evacuated. Client and head office are then notified and ICH Asbestos Policy is followed.	5	1	5			
COSHH Consequence Exposure to harmful substance causing acute and chronic ill heal	16	Employees are required to follow the documented ICH COSHH risk assessment and Safety Data Sheet when working with hazardous chemicals. Appropriate PPE is provided and worn in the form of gloves, safety glasses and hard hats. Specific PPE is worn by the employee.	4	1	4			

Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8			
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8			
Physical injury / risk of disease Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances without using the correct protection, creams etc.	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis. c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.	4	2	8			
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available.	2	2	4			

Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6			
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2			
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3			
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4			

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Dust

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

People with Disabilities

Description:

Working in and around dust

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Working around or causing construction dust Consequence Respiratory irritation and allergies. Dust can cause irritation to the eyes, noses and throat. Dust can cause difficulty breathing and can trigger coughing and sneezing	12	When operating plant that causes dust, the operative is to refer to the specific risk assessment for this plant. Operatives are to consider using a different method of work altogether when operating tools that create dust. The right size building materials are to be used so that less cutting or preparation is needed. Where possible, operatives are to use a less powerful tool that creates less dust, brick breaking tools such as hammers and bolsters and clock breakers are to be used where possible instead of grinders and cutting tools Designated cutting stations will be allocated in areas which are isolated and	4	2	8			

		well ventilated. When alternatives cannot be used and dust control not sufficient, water is to be used for the entire length of the task or/and local exhaust ventilation system (LEV) will be used. Operatives are to maintain a high level of housekeeping, using filter vacuums for debris, bagging and removing waste according to local regulations and the site management plan.					
--	--	---	--	--	--	--	--

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Air Conditioning Split-System Replacement

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

To replace air conditioning split systems.

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Asbestos Consequence Exposure to asbestos fibers causing asbestos related illness.	20	All operatives are given suitable training relating to asbestos awareness. If fibrous materials are encountered, work is stopped, and the area is evacuated. Client and head office are then notified and ICH Asbestos Policy is followed.	5	1	5			
COSHH Consequence Exposure to harmful substance causing acute and chronic ill heal	16	Employees are required to follow the documented ICH COSHH risk assessment and Safety Data Sheet when working with hazardous chemicals. Appropriate PPE is provided and worn in the form of gloves, safety glasses and	4	1	4			

		hard hats. Specific PPE is worn by the employee.					
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8		
Physical injury / risk of disease Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances without using the correct protection, creams etc.	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis. c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.	4	2	8		
Refrigerant gases Consequence - Cold burns - Explosion - Toxic - Asphyxiation	16	a) Engineers are given suitable information, instruction and training in handling refrigerants. b) Engineer to wear appropriate PPE (nitrile gloves and goggles) when handling refrigerants.	4	1	4		
Slips, trips and falls	6	Staff have been provided with sufficient information, instruction and training.	2	2	4		

Consequence Bodily injuries resulting in strains, sprains, broken bones etc.		Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.					
Working at height Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	a) Engineers are trained in the safe use of ladders and stepladders. b) IPAF training for using a MEWP is provided to all engineers. c) Working area is cordoned off when working at height when deemed necessary by their risk assessment. d) Engineers are required to follow the documented ICH policy for working at height. e) Engineers to wear bump caps and safety glasses when working at height above suspended ceilings.	3	2	6		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	12	Limit the 8 hour exposure to less than 85 dBA. at 100DbA less than 15 minutes of exposure. Ear defenders supplied and used when needed.	4	3	12		
Workplace stress including mental health related issues	9	Staff fully understand what their duties and responsibilities are.	3	2	6		

Consequence Excessive workloads resulting in mental health related issues		There is a 'No Bullying' policy in place. Appointed person(s) trained as a mental health first aider.					
Confined spaces Consequence Asphyxiation through lack of oxygen, lack of emergency response resulting in worsened injuries, falls from height etc.	16	a) Suitable emergency procedures are arranged with the client when working in confined spaces. b) Suitable access / egress is maintained at all times. c) Sufficient lighting should be in place at all times. d) CO2 extinguishers are not used when working in a confined space	4	2	8		
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4		
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Hand Tools Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate.	2	1	2		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Electrical Work (Dead Circuit)

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

To carry out general electrical work.

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Asbestos Consequence Exposure to asbestos fibers causing asbestos related illness.	20	All operatives are given suitable training relating to asbestos awareness. If fibrous materials are encountered, work is stopped, and the area is evacuated. Client and head office are then notified and ICH Asbestos Policy is followed.	5	1	5			
Confined spaces Consequence Asphyxiation through lack of oxygen,	16	a) Suitable emergency procedures are arranged with the client when working in confined spaces. b) Suitable access / egress is maintained at all times.	4	2	8			

lack of emergency response resulting in worsened injuries, falls from height etc.		c) Sufficient lighting should be in place at all times. d) CO2 extinguishers are not used when working in a confined space					
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	16	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking. Lone workers to regularly be in contact with management team and follow ICH Lone Worker Policy.	4	2	8		
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.	2	2	4		
Working at height Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	a) Engineers are trained in the safe use of ladders and stepladders. b) IPAF training for using a MEWP is provided to all engineers. c) Working area is cordoned off when working at height when deemed necessary by their risk assessment.	3	2	6		

		d) Engineers are required to follow the documented ICH policy for working at height. e) Engineers to wear bump caps and safety glasses when working at height above suspended ceilings.					
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Hand Tools Consequence Repetitive use of hand tools causing muscle strain	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	2	1	2		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	9	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	3	1	3		

Use of Power Tools Consequence Default equipment malfunctioning causing an injury to user	12	Visually check condition of leads and plugs before use. All portable electrical hand tools will be regularly inspected and PAT tested by a competent person. Use 110v or battery tools or RCD where practicable. Loose clothing, jewellery and long hair to be kept clear of moving parts. Minimise the time individuals use heavy equipment (e.g. job rotation). Wear appropriate PPE (eg safety footwear & eye protection, masks etc) Ensure work area is free (as is practicable) from trailing cables, tools, materials, debris and spills. Only use tools that are appropriate for the job and used in accordance with manufacturer's instructions. Power tools to be securely stored when not in use.	4	1	4		
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	1	5		
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Noise	9	Limit the 8 hour exposure to less than 85 dBA. at 100DbA less than 15 minutes of exposure.	3	1	3		

Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.		Ear defenders supplied and used when needed.					
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Hot works

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Contractors

Others

People with Disabilities

Description:

Hot works, such as welding, cutting, and soldering.

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
General hazards Consequence - Lighting - Housekeeping - Exposure to harmful substances - Temperature	16	a) Portable electrical appliances are periodically tested. b) The work area is kept free from obstructions and good housekeeping standards are maintained. c) Appropriate lighting is provided in all areas. d) Office are adequately heated by central heating radiators/and air conditioning system/wall mounted electric storage radiators.	4	2	8			
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place	8	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	3	12			

to respond to an incident, resulting in worse injury or ill health							
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	12	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	4	2	8		
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		

Electricity	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10			
Consequence Electrocution Death								
Slips, trips and falls	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.	2	2	4			
Consequence Bodily injuries resulting in strains, sprains, broken bones etc.								

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:
Generic replace Electric Water Heater

Assessment Date:
2 Mar 2026

Expiry / Review Date:
4 Mar 2027

Conducted Site:
ICH - Leeds

Risk Assessment Owner:
Laura Stead

Persons Affected/Involved:
Employees
Visitors
Contractors
General Public
Others
Agency Workers
People with Disabilities

Description:
To replace faulty electric water heater in cupboard.

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likeli hood	Rating		Likeli hood	Rating
Asbestos Consequence Exposure to asbestos fibers causing asbestos related illness.	20	All operatives are given suitable training relating to asbestos awareness. If fibrous materials are encountered, work is stopped, and the area is evacuated. Client and head office are then notified and ICH Asbestos Policy is followed.	5	1	5			
COSHH Consequence Exposure to harmful substance causing acute and chronic ill heal	16	Employees are required to follow the documented ICH COSHH risk assessment and Safety Data Sheet when working with hazardous chemicals. Appropriate PPE is provided and worn in the form of gloves, safety glasses and hard hats. Specific PPE is worn by the employee.	4	1	4			

Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8		
Physical injury / risk of disease Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances without using the correct protection, creams etc.	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis. c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.	4	2	8		
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available.	2	2	4		

Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Noise Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.	9	Limit the 8 hour exposure to less than 85 dBA. at 100Dba less than 15 minutes of exposure. Ear defenders supplied and used when needed.	3	1	3		
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Safe Electrical Isolation

Assessment Date:

2 Mar 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

Ensuring that an electrical system or circuit is completely de-energised before working on it. Following the ICH Safe Isolation Policy.

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Asbestos Consequence Exposure to asbestos fibers causing asbestos related illness.	20	All operatives are given suitable training relating to asbestos awareness. If fibrous materials are encountered, work is stopped, and the area is evacuated. Client and head office are then notified and ICH Asbestos Policy is followed.	5	1	5			
Confined spaces Consequence Asphyxiation through lack of oxygen,	16	a) Suitable emergency procedures are arranged with the client when working in confined spaces. b) Suitable access / egress is maintained at all times.	4	2	8			

lack of emergency response resulting in worsened injuries, falls from height etc.		c) Sufficient lighting should be in place at all times. d) CO2 extinguishers are not used when working in a confined space					
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place to respond to an incident, resulting in worse injury or ill health	16	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking. Lone workers to regularly be in contact with management team and follow ICH Lone Worker Policy.	4	2	8		
Slips, trips and falls Consequence Bodily injuries resulting in strains, sprains, broken bones etc.	6	Staff have been provided with sufficient information, instruction and training. Documented records are available. Mats are in place at the entrances to the offices. The floor area is in a good state of repair. Floors etc. are cleaned regularly by outside contractors and/or by employees. If required, "Wet Floor" signs are available. Staff clean as they go e.g. clear up spillages immediately. Mops, brushes etc are available. If required, "Wet Floor" signs are available. Skips / bins are provided for waste. These are emptied at regular intervals. Trailing cables are kept to a minimum and / or cable covers are in place. Suitable hand rails are fitted to stairways.	2	2	4		
Working at height Consequence Falls from height resulting in serious injury including broken bones, concussion, impalement etc.	12	a) Engineers are trained in the safe use of ladders and stepladders. b) IPAF training for using a MEWP is provided to all engineers. c) Working area is cordoned off when working at height when deemed necessary by their risk assessment.	3	2	6		

		d) Engineers are required to follow the documented ICH policy for working at height. e) Engineers to wear bump caps and safety glasses when working at height above suspended ceilings.					
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6		
Hand Tools Consequence Repetitive use of hand tools causing muscle strain	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.	2	1	2		
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	9	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	3	1	3		

Use of Power Tools Consequence Default equipment malfunctioning causing an injury to user	12	Visually check condition of leads and plugs before use. All portable electrical hand tools will be regularly inspected and PAT tested by a competent person. Use 110v or battery tools or RCD where practicable. Loose clothing, jewellery and long hair to be kept clear of moving parts. Minimise the time individuals use heavy equipment (e.g. job rotation). Wear appropriate PPE (eg safety footwear & eye protection, masks etc) Ensure work area is free (as is practicable) from trailing cables, tools, materials, debris and spills. Only use tools that are appropriate for the job and used in accordance with manufacturer's instructions. Power tools to be securely stored when not in use.	4	1	4		
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10		
Bad or inappropriate lighting Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.	6	Correct lighting is established prior to work by the dynamic risk assessment. Additional lighting to be ordered and used correctly if required.	2	1	2		
Noise	9	Limit the 8 hour exposure to less than 85 dBA. at 100DbA less than 15 minutes of exposure.	3	1	3		

Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.		Ear defenders supplied and used when needed.					
Adverse weather Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing. Plenty of fluids available and take regular breaks Warm clothes provided by ICH	4	1	4		

	Risk Rating Matrix				
	Trivial	Minor Injury	7+ Day Injury	Major Injury	Incapacity/Death
Certain	5	10	15	20	25
Probable	4	8	12	16	20
Possible	3	6	9	12	15
Unlikely	2	4	6	8	10
Highly Unlikely	1	2	3	4	5

Risk Assessment Name:

Generic Working at Height including Use of Scaffolding Roof Work

Assessment Date:

12 Feb 2026

Expiry / Review Date:

4 Mar 2027

Conducted Site:

ICH - Leeds

Risk Assessment Owner:

Laura Stead

Risk Assessment Version:

1

Persons Affected/Involved:

Employees

Visitors

Contractors

General Public

Others

Agency Workers

People with Disabilities

Description:

General working at height including use of scaffolding & roof work

Identified Hazard	Risk with no Controls	Controls in Place	Based on Controls in Place			Additional Control Measures	With Additional Controls	
			Worst Case	Likelihood	Rating		Likelihood	Rating
Emissions from stacks, extraction ducts or electrical systems Consequence Exposure to harmful substance causing acute and chronic ill health	12	a) Checks made prior to site visit to establish if such things are in the vicinity of the work area. b) Such work is avoided if necessary and a dynamic risk assessment would be undertaken.	4	1	4			
Lone working Consequence Risk of injury whilst working alone and not having adequate monitoring in place	12	a) Engineers are required to follow the documented ICH Lone Worker policy. Single person work is prohibited when there is the risk of the cold store door self-locking.	4	2	8			

to respond to an incident, resulting in worse injury or ill health							
Manual handling Consequence Incorrect lifting of items resulting in musculoskeletal injuries or alike	16	Employees are given suitable information, instruction and training in manual handling. Suitable lifting aids, such as lift truck and sack barrows, are available where required. For jobs involving difficult manual handling, those involved in the lift appropriately discuss beforehand and agree a safe system of work. The acronym TILE is understood by all engineers.	4	2	8		
Physical injury / risk of disease Consequence Both physical and ill health affects from not wearing the correct PPE or coming into contact with harmful substances without using the correct protection, creams etc.	16	a) PPE is provided in the form of: - Safety shoes - Safety glasses - Protective gloves - Ear defenders - Bump caps - Overalls c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis. c) Engineers use barrier cream, gloves and maintains routine hygiene to help prevent dermatitis.	4	2	8		
Pitched Roof Work Consequence Increased chance of falling from roof edge, slipping down the roof etc. resulting in serious injury or death	20	a) Condition of roof is assessed for fragile roof warnings prior to completing work. Two man operation-crawl boards and edge protection to be provided where applicable. b) Such work is avoided unless appropriate access and protection measures are in place including edge protection, walking boards or fall arrest system.	5	2	10		
Podium and Mobile Towers Consequence - Falling through the barrier or gate - Overturning of equipment - Tools etc. falling onto person(s) below. - Slipping from ladder rungs or steps - Collapse of equipment	20	a) Checks are undertaken to ensure that the gate or barrier is always closed prior to commencement of work when deemed necessary by their risk assessment. b) Checks carried out to ensure wheels or feet are in contact with a firm surface. c) Equipment is not used on uneven, slippery, sloping or soft ground.	5	1	5		

		d) Outriggers are used where required. e) Castors are locked in position. f) Where required exclusion zones are established around / under the work area. g) Where required lanyards / toolbelts used to retain equipment when working at height. h) The equipment is not moved whilst operators are on the tower. i) Manufacturer's instructions always adhered to. j) Work is accessible without overreaching. k) Equipment is only erected, dismantled and altered in accordance with manufacturer's guidance.					
Roof Work Consequence Fall from roof edge, through skylights etc. resulting in serious injury or death	20	a) Short duration jobs acceptable from the roof centre if condition of roof is assessed. b) Engineer will cover or barrier all roof lights and use crawl boards/roof ladders as necessary. c) No work is undertaken within 2 meters of an unprotected edge. d) When working at the edge of a roof and there is no edge protection, a fall arrest system is implemented.	5	2	10		
Scaffolding Consequence Falling off or through the scaffolding, collapse under incorrect erection etc.	15	a) Before going on the scaffolding do a visual check to make sure the scaffold is erected properly. b) Check the Scaff tag has been completed and the scaffold is fit for use. c) Connect to the scaffold using harness and lanyard. d) Carry out a dynamic risk assessment before starting all work. e) When finished, engineers using the scaffold will turn the Scaff tag around to show the RED side. This will indicate that work has finished.	5	2	10		

Step Ladders / Ladders / Telescopic & Combination Ladders / Mobile Steps	9	a) Staff have been provided with sufficient information, instruction and training. Documented records are available. b) Ladders (if used) are only used for low-risk, short duration work. c) Domestic step ladders / ladders are not used. Only industrial / tradesmen type step ladders / ladders are used. d) Regular inspections undertaken of the step ladders / ladders / mobile steps etc. Documented records are available. e) Users ensure step ladder / ladders are not overloaded. f) Where required exclusion zones are established around / under the work area. g) Where required lanyards / toolbelts used to retain equipment when working at height.	3	2	6			
Consequence □ Falling from the step ladder / ladder / mobile steps e.g. over- reaching, slipping, equipment not placed on level ground, ladder not properly secured, ladder etc. being struck by a moving vehicle. □ Failure of the step ladder / ladder / mobile steps e.g. due to inadequate maintenance, overloading etc. □ Tools etc. falling onto person(s) below.								
Workplace stress including mental health related issues Consequence Excessive workloads resulting in mental health related issues	9	Staff fully understand what their duties and responsibilities are. There is a 'No Bullying; policy in place. Staff are able and encouraged to talk confidentially to their managers if they are unhappy with the situation at work. Appointed person(s) trained as a mental health first aider.	3	2	6			
Electricity Consequence Electrocution Death	20	Suitable training provided to all engineers covering general risks relevant to the business. Portable electrical appliances are periodically tested. Engineers are required to use an approved and calibrated tester to check for voltage. All live testing must follow the documented Electrical Isolation & Live Working Policy.	5	2	10			

Bad or inappropriate lighting	6	Correct lighting is established prior to work by the dynamic risk assessment.	2	1	2		
Consequence Unable to see properly and causing injury such as fractures and sprains by tripping and falling objects unable to see.		Additional lighting to be ordered and used correctly if required.					
Noise	9	Limit the 8 hour exposure to less than 85 dBA. at 100DbA less than 15 minutes of exposure.	3	1	3		
Consequence Noise at work can cause temporary or permanent hearing damage that is disabling. This can be gradual from exposure to noise over time or caused by sudden, extremely loud noises.		Ear defenders supplied and used when needed.					
Adverse weather	12	Dynamic risk assessment used to assess the weather conditions prior to works commencing.	4	1	4		
Consequence Unsafe working conditions- too hot leading to sunstroke and too cold leading to dangerous surface conditions and chill blains		Plenty of fluids available and take regular breaks Warm clothes provided by ICH					
Hand Tools	6	All hand tools to be routinely inspected pre use to ensure it remains safe to use	2	1	2		
Consequence Incorrect use of hand tools leading to cuts and lacerations on the users body		Tools must not be modified for a particular job, instead obtain the correct tool. Tools must not be abused e.g. screwdrivers used as chisels. Specialist tools to be made available where appropriate. Worn out tools to be replaced e.g. chisel head with a mushroomed top must not be used.					