

SOP-08 — Lock-Out / Tag-Out (LOTO)

Plant: Shakti Petrochem Unit-2 | **Applies To:** All | **Revision:** Rev 5 | **Last Reviewed:** 2025-02-20

Procedure Steps

1. Identify all energy sources. Isolate, lock, tag, and verify zero energy before work.